Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

NM OUCCONSERVATION

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

☐ Water Shut-Off

Venting and/or Flari

■ Well Integrity

Other

ARTESIA DISTRICT **BUREAU OF LAND MANAGEMENT** BY NOTICES AND REPORTS ON WELLS PAR 0 2 2015

5. Lease Serial No. NMLC061705A

SUNDKI N	OTICES WIND KI	EPURIS	OM MEL	LO ' '
Do not use this	form for proposa	ls to drill	or to re-en	ter an
abandoned well.	Use form 3160-3	(APD) for	r such pro	posals.

6. If Indian, Allottee or Tribe Name

apandoned we			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.		7. If Unit or CA/Agreement, Name and/or No. 891000303E	
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other		8. Well Name and No. POKER LAKE UNIT 078	
Name of Operator BOPCO LP	Contact: TRACIE J CHERRY E-Mail: tjcherry@basspet.com	9. API Well No. 30-015-27536	
3a. Address P O BOX 2760 MIDLAND, TX 79702	3b. Phone No. (include area code) Ph: 432-221-7379	10. Field and Pool, or Exploratory POKER LAKE; DELAWARE SW	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, and State	
Sec 25 T24S R30E NENE 660	OFNL 660FEL	EDDY COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE	CE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

☐ Plug Back

Deepen

□ Fracture Treat

■ New Construction

□ Plug and Abandon

BOPCO, LP respectfully submits this sundry notice to report the volume flared for 90-days on the referenced agreement. Wells contributing to the flaring volume are as follows:

☐ Acidize

☐ Alter Casing

□ Casing Repair

☐ Change Plans

Convert to Injection

Lease number/well/API

■ Notice of Intent

Subsequent Report

☐ Final Abandonment Notice

NMLC061705B / POKER LAKE UNIT 100 / 30-015-27961-00-S1 NMLC061705B / POKER LAKE UNIT 103 / 30-015-27919-00-S1 State - E2206 / POKER LAKE UNIT 105 / 30-015-27895-00-S1 NMLC061705B / POKER LAKE UNIT 106 / 30-015-27920-00-S1 NMNM0157779 / POKER LAKE UNIT 108 / 30-015-28086-00-S1 NMNM0157779 / POKER LAKE UNIT 111 / 30-015-28087-00-S1 State - B10685 / POKER LAKE UNIT 114 / 30-015-28102-00-S1

☐ Production (Start/Resume)

☐ Temporarily Abandon

□ Reclamation

☐ Recomplete

☐ Water Disposal

14. I hereby certify that th	e foregoing is true and correct. Electronic Submission #222915 verifie For BOPCO LP, se Committed to AFMSS for processing	nt to th	e Carlsbad	•	
Name (Printed/Typed)	TRACIE J CHERRY	Title	REGULA	TORY ANALYST	
Signature	(Electronic Submission)	Date	10/14/20	ACCEPTED FOR RECORD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By		Title		FEB 20 2019	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office		BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #222915 that would not fit on the form

32. Additional remarks, continued

STATE - B10685 / POKER LAKE UNIT 115 / 30-015-28180-00-S1 NMLC061705A / POKER LAKE UNIT 118 / 30-015-29213-00-S1 NMLC061705A / POKER LAKE UNIT 78 / 30-015-27536-00-S1 NMLC061705A / POKER LAKE UNIT 80 / 30-015-27537-00-S1 NMLC061705A / POKER LAKE UNIT 82 30-015-27752-00-S1 NMNM030453 / POKER LAKE UNIT 82 30-015-27752-00-S1 NMNM0506A / POKER LAKE UNIT 83 / 30-015-27753-00-S1 STATE NMB10685 / POKER LAKE UNIT 84 / 30-015-29103-00-S1 NMLC061705B / POKER LAKE UNIT 85 / 30-015-27911-00-S1 NMLC061705B / POKER LAKE UNIT 86 / 30-015-27912-00-S1 NMLC061705B / POKER LAKE UNIT 87 / 30-015-27986-00-S1 NMLC061705B / POKER LAKE UNIT 87 / 30-015-27797-00-S1 NMNM030453 / POKER LAKE UNIT 92 / 30-015-27797-00-S1 NMNM030453 / POKER LAKE UNIT 92 / 30-015-27797-00-S1 NMNM030453 / POKER LAKE UNIT 93 / 30-015-27797-00-S1 NMNM030453 / POKER LAKE UNIT 99 / 30-015-32823-00-S1

Intermittent flaring was necessary due to restricted pipeline capacity at respective sales points.

4134 MCF was flared for the period Sept-Nov 2012