Form 3160-5 (March 2012)

# UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

			Expires:	Octol
7	9000	Social	Mo	

BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter all abandoned well. Use Form 3160-3 (APD) for such proposal				5. Lease Serial No.	
				NM 025527	
				6. If Indian, Allottee or Tribe Name	
. SUBMIT I	N TRIPLICATE – Other i		7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Gas Well	Other		8. Well Name and No.  Willis Federal Com 1		
2. Name of Operator  Murchison Oil & Gas, Inc			9. API Well No. 30-015-22987		
3a. Address 3b. Phone No. (include area code)				10. Field and Pool, or Exploratory Area	
7250 Dallas Pkwy, #1400, Plano TX 75024   972-931-0700				Logan Draw; Morrow (Gas)	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2130 FNL 1650 FEL, 28-17S-27E				11. County or Parish, State  Eddy County, NM	
12. CHECK A	PPROPRIATE BOX(ES	S) TO INDICATE NA	ATURE OF NOTIC	E, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION			TYPE OF ACTI	ON	
57	Acidize	Deepen Deepen	Production (Start	t/Resume)	
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
Tinal Ahandar Nati	Change Plans	Plug and Abandon	Temporarily Aba	andon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
4. Spot 20 sxs cement plus. 5. Spot 23 sxs cement plus. 6. Perf and squeeze 35 sx 7. Perf and squeeze 35 sx 8. Perf and squeeze 35 sx 9. Cut and pull 1,725' 5-1 10. Spot 45 sxs cement plus. 11. Spot 110 sxs cement fill. 12. Cut off wellhead and sceptifical systems.	g from 7,440' - 7,220' cement plug from 4, cement plug from 4,, cement plug from 2,' /2'' casing. ug @ 1,775' - 1,675'. rom 400' to surface.	'. 890' - 4,740'. WO 220' - 4,080'. WO 720' - 2,600'. WO WOC and tag plu	C and tag plug. C and tag plug. Ig.	SEE ATTACHED FOR CONDITIONS OF APPROVAL Page 3. Changes n and clean location. Proceduces  NM OIL CONSERVATION ARTESIA DISTRICT APR 27 2015	
14. I hereby certify that the foregoing	is true and correct. Name (Print	ted Typed)	<del> </del>		
Gary Cooper  Title Vice President Operations  RECEIVED				t Operations	
la	6				
Signature	THIS SPACE	FOR FEDERAL		FICE USE	
Approved by	0 0				
Conditions of approval, if any, are attact that the applicant holds legal or equitab	le title to those rights in the sub	es not warrant or certify	Office 162	Date 4-21-15	
entitle the applicant to conduct operation it le 18 U.S.C. Section 1001 and Title false, fictious or fraudulent statements	43 U.S.C. Section 1212, make i	it a crime for any person kn atter within its jurisdiction.	owingly and willfully to	make to any department or agency of the United States any	
(Instructions on page 2)			· · · · · · · · · · · · · · · · · · ·		

### MURCHISON OIL & GAS, INC.

#### Willis Federal Com #1

API# 30-015-22987 GL = 3424 ft

#### **Surface Casing**

13 3/8" 48 lb/ft H-40 Setting Depth – 350 ft

#### **Intermediate Casing**

8 5/8" 24 lb/ft J-55 Setting Depth – 1725 ft

#### **Production casing**

5 1/2" 17 lb/ft K-55 Setting Depth - 9589 ft

#### TD - 9590 ft MD/TVD

PBTD - 9507 ft MD/TVD

#### **Perforated Interval:**

9284-89' (6)

9291-94' (4)

9296-99' (4)

9308-18' (11)


9401' (1)

9445-58' (14)

9465-70' (6)

9472-74' (3)

9476-90' (15)



400' - 0' 110 sx cmt

1775' - 1675' 45 sx cmt

2720' - 2600' 35 sx cmt

4220' – 4080' 35 sx cmt

4890' - 4740' 35 sx cmt

7440' - 7220' 25 sx cmt

8460' - 8260' 20 sx cmt 8870' - 8670' 20 sx cmt

9250' CIBP & 20 sx cmt

Murchison Oil & Gas Inc. 7250 Dallas Pkwy, #1400 Plano, TX 75024

RE: NMNM025527; Willis Federal Com NO. 1 2130' FNL & 1650' FEL, Sec. 28, T17S-R27E Eddy County, New Mexico

Plugging and Abandonment, Conditions of Approval, Changes to Original Submittal:

- 1. No change
- 2. 25 sack Class H cement plug minimum.
- 3. 25 sack Class H cement plug from 8691'-8501' (Top of Strawn).
- 4. 25 sack Class H cement plug from 8059'-7879' (Top of Canyon).
- 25 sack Class C cement plug from 6265'-6105' (Top of Wolfcamp).
   Add plug: 25 sack Class C cement plug from 6039'-5879' (DVT). WOC and tag.
- 6. Perf and squeeze adequate Class C cement plug from 5014'-4864' (Top of Abo). WOC and tag.
- 7. Perf and squeeze adequate Class C cement plug from 3105'-2975' (Top of Yeso). WOC and tag.
- 8. Perf and squeeze adequate Class C cement plug from 2841'-2711' (Top of Glorieta). WOC and tag.
- 9. Cut and pull5-1/2" casing @ 1775'.
- 10. Spot adequate Class C cement from 1825'-1675' (stub and shoe). WOC and tag.
- 11. No change
- 12. No change

If any questions and/or concerns, contact Jim Amos @ 575-234-5909 or 575-361-2648 (cell).

J. Amos 4/21/15

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11