

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Devon Energy	Contact: Daniel Suniga
Address: P. O. Box 250 Artesia, NM 88211	Telephone No.: 575-390-5850
Facility Name: Apache 25 #8 SWD	Facility Type: SWD

Surface Owner	Mineral Owner	Lease No. API #30-015-33439 2RP-1384
---------------	---------------	---

LOCATION OF RELEASE

Unit Letter G	Section 25	Township 22S	Range 30E	Feet from the 1980'	North/South Line North	Feet from the 1650'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release: Produced Fluids	Volume of Release - 520 bbls	Volume Recovered 520 bbls
Source of Release: Water Pump Malfunctioned	Date and Hour of Occurrence 10/13/12, 4:00 pm	Date and Hour of Discovery 10/14/12, 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Daniel Suniga, Production Foreman BLM / Jennifer Van Curen & OCD / Mike Bratcher	
By Whom? Jerry VanNatta, Lease Operator	Date and Hour 10/14/2012, 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.* A water pump at the Apache 25 No. 8 SWD malfunctioned causing the water tanks to overflow into the lined containment area resulting in a 520 barrel produced water release. The water pump was re-set and returned back to service. A vacuum truck was immediately called to the location and recovered 520 barrels of produced water.

Describe Area Affected and Cleanup Action Taken.* Talon/LPE was contracted for the correction of this release. The impacted area from this release was excavated to a depth of 3-feet deep, analytical testing was completed. Following BLM approval of the confirmation samples, the excavation was backfilled to grade using new material, contoured to match the surrounding location and seeded using BLM mixture No. 2.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Gracie Bustamante	Approved by District Supervisor: 	
Title: Field Admin Support	Approval Date: 4/23/15	Expiration Date: N/A
Date: 4/2/2013 Phone: 575-746-5561	Conditions of Approval: Final	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-1384