

Submit 1 Copy To Appropriate District Office

State of New Mexico

Form C-103

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Revised July 18, 2013

WELL API NO. 30-015-37161
5. Indicate Type of Lease STATE [] FEE [X]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Puckett North
8. Well Number 7
9. OGRID Number 025111
10. Pool name or Wildcat Maljamar/Grayburg/San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [X] Gas Well [] Other []
2. Name of Operator Hudson Oil Company of Texas
3. Address of Operator 616 Texas Street, Fort Worth, Texas 76102
4. Well Location Unit Letter C : 990' feet from the North line and 1650' feet from the West line
Section 13 Township 17 South Range 31 East NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
OTHER: Inter-Well Communication [X]

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

This well was fractured in the Grayburg/San Andres formations on 3/17/10 and 4/22/10. On 4/23/10 the Grayburg/San Andres production from the Puckett North #3 Well, API #30-015-36633, located in Section 12, T17S - R31E, 810' FSL and 2260' FWL, Unit N, Eddy County, dropped off dramatically, indicating we had communicated with, or "hit", the wellbore during the frac treatment. Over the next several days, the production from the "hit" well returned to normal, indicating the reservoir had equalized.

Spud Date: 2/10/2010

Rig Release Date: 2/18/2010

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 4/28/15

Type or print name E. Randall Hudson III E-mail address: rhudson@hudsonoil.com PHONE: 817-336-7109

For State Use Only

APPROVED BY: [Signature] TITLE [Signature] DATE 5/7/15

Conditions of Approval (if any):