

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

MAY 13 2015
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1513441350		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		Contact: Tony Savoie		
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329		
Facility Name: JRU-106H Flow line, the spill is 2003 ft. East of the well pad. UL "J"		Facility Type: Exploration and Production		

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-015-37063
------------------------------------	------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	36	22S	30E					Eddy

Latitude N 32.34644° Longitude W 103.83291°

NATURE OF RELEASE

Type of Release: Crude oil	Volume of Release: 24 bbls	Volume Recovered: 20
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence: 5/3/15, time unknown	Date and Hour of Discovery: 5/3/15 at approximately 2:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson, company e-mail	
By Whom? Tony Savoie	Date and Hour: 5/3/15 at 6:39 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The flow line developed a leak due to corrosion, a temporary leak clamp was placed on the affected area until the well could be shut down and a joint of pipe replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 1,020 sq.ft. of pasture. All of the free standing fluid was picked up with a vacuum truck.
The stained area was left as is pending the final remediation.
The spill area will be cleaned up in accordance to the NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: [Signature]	
Title: Waste Management and Remediation Specialist		Approval Date: 5/14/15	Expiration Date:
E-mail Address: tasavoie@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 5/13/15 Phone: 432-556-8730		SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 6/15/2015

2RP-2999