

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 20 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Zircon Compressor Facility / State HL #1	Facility Type: Oil producing Well

Surface Owner: State	Mineral Owner: State	API No. 30-015-23065
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 1	Township 19S	Range 29E	Feet from the 660'	North/South Line South	Feet from the 1980'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.68388 Longitude -104.03062

NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 20 bbls	Volume Recovered: N/A
Source of Release: Compressor catch tank	Date and Hour of Occurrence 5-19-15	Date and Hour of Discovery 5-19-15 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD	
By Whom? Zack Thomas	Date and Hour 5-19-15 2:18 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Cause of the leak- Dump failure on well separator causing fluid to go down gas line to Zircon Compressor Facility causing catch tank to be over filled.
Dump on separator was fixed to stop the release.

Describe Area Affected and Cleanup Action Taken.*

Leaked fluid affected the pad surface around the catch tank and also ran off location to the west an estimated 200 yards in to the pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 5/22/15	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 5-20-15	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 6/22/15	

* Attach Additional Sheets If Necessary

Attached ☐

2RP-3009