District 1
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action													
nAB1	51425	3266			/	OP	PERAT	OR			Report	П	Final Report
Name of Co	ompany I			E.L. Gonzales									
		nder Blvd F		M 88240		No. 575-738-							
Facility Nar	ne H.E. W	Fac	cility Typ	e Oil Produc	er			•					
Surface Ow	nor Fodos					A DI No	20.015	2052	0				
Surface Ow	nei regei		API No. 30-015-28538										
	<u> </u>			LOCA				EASE					
							uth <u>Line</u> ith	Feet from the 1440	East	West Line East	County	Eddy	
Latitude 32.8456 Longitude,-103.87019													
NATURE OF RELEASE													
Type of Rele	ase Oil / Pi	V	Volume of Release 1 bbl / 1 bbl Volume Recovered 1 bbl / 1 bbl										
Source of Re	lease Poly I							Hour of Discovery 15 2:30pm					
Was Immedia	ate Notice G		If YES, To Whom?										
es sugest that it years in	ما والإن المدينة	-	NM OIL CONSERVAT										
By Whom?		Date and Hour ARTESIA DIS											
Was a Watercourse Reached? ☐ Yes ☑ No							If YES, Volume Impacting the Watercourse. MAY 2 1 2015						L 2015
If a Watercourse was Impacted, Describe Fully.*													
,											R	ECEI	VED
													•
D 2. C.	CD11-		Eal A Ala	T-1 * M:-	<u> </u>	(422	3)202 422	2 41 149 6	4 14 1		11.		1. 3. 131.
Describe Cause of Problem and Remedial Action Taken.* Mario Garcia (432)202-4333 with M&G rental tools was avoiding driving through mud puddle in road and drove off road and over flow lines. Flow line on WB#92 was damaged releasing fluid on the road into a puddle of fresh water, adjacent shrubbery, and a small amount into the pasture. Total fluid released was approximately 2 bbl total fluid. Mario Garcia called in Double R trucking to pick													
up liquids and will accept full liability and cost for the spill. Manuel with BTS (575) 942-8307 repaired the line.													
Describe Area Affected and Cleanup Action Taken.* Puddle was apprx 30ft x 20ft, area affected in pasture was to the south apprx. 2ft x 30ft. Michael Burton with DFSI (575)942-4115 will handle further assessment.													
·													
	٧												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
								OIL CON	ISERV	ATION	DIVISION	ZNC	フ
Signature:							,/ //						
Signature.		A	and by C		?!!:-	//							
Printed Name	Аррг	roved by E	Invironmental 5	specians	1/1/20	-h/	7	· .					
Title: Produc	tion Superv	isor				Appr	roval Date:	5/22	5	Expiration [Date: N	A	
									 L.				
E-mail Addres	ss: elgonzal	es@linnenerg	y.com			Cond	ditions of A	Approval: per O.C.D.	Dulac	& Guidal	Attached		
Date: 05/12/2	2015		Phone:	505-504-8002	31	JBM	AIT REM	IEDIATION	PROP	OSAL NO	11162		
Attach Additio	nal Sheets	If Necessary						: 1/22	5		• • • • • • • • • • • • • • • • • • • 	1RI	D-3012
												41 11	, J