Office Office		lew Mexico			Form C-103
District I – (575) 393-6161	Energy, Minerals a	nd Natural Res	ources		evised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			I .	WELL API NO.	
District II - (575) 748-1283 B11 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			 	30-015-03206	
District III – (505) 334-6178 1220 South St. Francis Dr.				 Indicate Type of Lease STATE ☒ 	FEE 🗌
1000 Rio Brazos Rd., Aztec, NM 87410	100 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sunu i O	1111 07505		o. State Off & Gas Lease E-7640	NO.
87505					
	CES AND REPORTS ON			7. Lease Name or Unit A	greement Name
(DO NOT USE THIS FORM FOR PROPOSE					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			L.	Old Loco Unit	
	Gas Well 🛛 Other			8. Well Number #005	
2. Name of Operator				9. OGRID Number	
Tandem Energy Corporation				236183	
3. Address of Operator				10. Pool name or Wildcat	
2700 Post Oak Blvd. Ste. 1000, Houston, TX 77056				Grayburg-Jackson	
4. Well Location	· · · · · · · · · · · · · · · · · · ·				
Unit Letter E:	2310 feet from the	North	line and	get from the _	West line
Section 32		17S Range	29E		County Eddy
	11. Elevation (Show who				Control of the contro
The state of the s	2618 GR	iner Dit, Idib, i	(1, O1, c.c.)		
THE STATE OF THE S	, <u> </u>			"" " " " " " " " " " " " " " " " " " "	N. TOPOTO, Law and Consider the Law Conference. Mr. 1995
12 Chook A	Appropriate Box to Inc	licate Nature o	f Notice P	enart or Other Data	
12. CHECK P	appropriate Box to file	iicate Nature 0	nonce, K	eport of Office Data	
NOTICE OF IN	ITENTION TO:		SUBS	EQUENT REPORT	OF:
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WOR			•		RING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI					
PULL OR ALTER CASING	MULTIPLE COMPL	_	NG/CEMENT		^
DOWNHOLE COMMINGLE	MOETH EE OOM E		10/0EMENT		
CLOSED-LOOP SYSTEM					
OTHER:		□ OTHE	R·		
	leted operations (Clearly			give pertinent dates inclu	ding estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or rec				Titladi Wolfoot	ang. u.i. or
1 1					
MIRO pulling unit.					
POOH with 2-3/8" tubing	J.				
	•	ing look			
RIH w/ packer to better locate the interval of casing leak					
RIH with 7" RBP and packer combination on tubing. Straddle the interval of the casing leak.					
Establish pump in rate, then squeeze with 35 sks cement.					
Drill out cement and pressure test to 500 psig.					
Wash down to top of RB	P and retrieve.				
RIH with injection packer and set around 2,450'. Pressure test to 500 psig.					
RDMO pulling unit and schedule a witnessed pressure test before returning the well to injection service.					
	-				
	· ·		<u> </u>		
Sand Data	. ·	alasaa Dataa			
Spud Date:	. ·	elease Date:			
Spud Date:	. ·	elease Date:			
	Rig R	, L _			
Spud Date: I hereby certify that the information	Rig R	, L _	y knowledge	and belief.	
	Rig R	, L _	y knowledge	and belief.	
I hereby certify that the information	Rig R	e to the best of m			
	Rig R	, L _			05/2015
I hereby certify that the information SIGNATURE	Rig R above is true and complete	e to the best of m	pecialist	DATE05/	
I hereby certify that the information SIGNATURE	Rig R above is true and complete	e to the best of m	pecialist	DATE05/	
I hereby certify that the information SIGNATURE . LOC	Rig R above is true and complete	e to the best of m	pecialist	DATE05/	
I hereby certify that the information SIGNATURE	Rig R above is true and complete	e to the best of m	pecialist	DATE05/	