	NM OIL CONSERVATION						
B SUNDRY	007) UNITED STATE DEPARTMENT OF THE I BUREAU OF LAND MANA SUNDRY NOTICES AND REPO		NTERIOR MAY 18 2(gement rts on wells		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM045275		
Do not use this form for proposals to drill or to re-enteRaDCEIVED abandoned well. Use form 3160-3 (APD) for such proposals.				ED	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well					8. Well Name and No. CONOCO AGK FEDERAL 3		
2. Name of Operator Contact: TINA HUERTA YATES PETROLEUM CORPORATIONE-Mail: tinah@yatespetroleum.com					9. API Well No. 30-015-26712		
3a. Address 105 SOUTH FOURTH STREI ARTESIA, NM 88210	3b. Phone No. (include area code) Ph: 575-748-4168 Fx: 575-748-4585).	10. Field and Pool, or Exploratory SOUTH DAGGER DRAW U PENN			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State				
Sec 26 T20S R24E NESE 19			EDDY.COUNT	Y, NM			
12. CHECK APP	ROPRIATE BOX(ES) TO) INDICATE 1	NATURE OF N	NOTICE, RE	EPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	Acidize Deepen Prod			Producti	ction (Start/Resume) 🔲 Water Shut-Off		
Subsequent Report	 Alter Casing Casing Repair 	Fractu	re Treat Construction	Reclama		Well Integrity	
Final Abandonment Notice	Change Plans Convert to Injection	🗖 Plug a	_		prarily Abandon		
 Describe Proposed or Completed Op If the proposal is to deepen direction: Attach the Bond under which the wo following completion of the involved testing has been completed. Final At determined that the site is ready for f Yates Petroleum Corporation MIRU any safety equipmer is connected to the purpose 	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation res bandonment Notices shall be file inal inspection.) plans to plug and abandon	give subsurface lo the Bond No. on f sults in a multiple ed only after all rec n this well as fo	cations and measu ile with BLM/BIA completion or reco quirements, includi Dllows:	red and true ver Required sub mpletion in a n ing reclamation	tical depths of all perti sequent reports shall be ew interval, a Form 31 , have been completed, RECLAN	nent markers and zones. e filed within 30 days 50-4 shall be filed once	
is cemented to the surface. 2. Set a CIBP at 7543 ft and cap it with 25 sx Class H cement. 3. Spot a 35 sx (170 ft) Class C cement plug from 6144 ft - 6311 ft. This will place a plug across Wolfcamp top. 4. Spot a 35 sx (170 ft) Class C cement plug from 5465 ft - 5635 ft. This will place a plug across stage tool. WOC and tag; reset if necessary. 5. Spot a 35 sx (170 ft) Class C cement plug from 3594 ft - 3764 ft. This will place a plug							
across Bone Spring top. 6. Spot a 35 sx (170 ft) Class			·	· · ·	ONDITIONS	OF APPROVAL	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #2 For YATES PETRO	94903 verified I	oy the BLM Well RATION, sent to	I Information the Carlsba	System		
Name(Printed/Typed) TINA HUERTA			Title REG REPORTING SUPERVISOR				
Signature (Electronic S	-	Data 02/12/00			MOCD		
Signature (Electronic S	THIS SPACE FO		Oate 03/13/20 OR STATE (<u></u>	5/20/13	
	1 /	•	0.1.0		<u> </u>	6.1.15	
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would enjyle the applicant to condu	not warrant or subject lease	Title CAL			Date 5-6-15		
Title 18 U.S. Section 1001 and Title 43 0 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a c tatements or representations as t	rime for any perso o any matter with	on knowingly and in its jurisdiction.	willfully to mak	e to any department or	agency of the United	

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

•.

Additional data for EC transaction #294903 that would not fit on the form

32. Additional remarks, continued

across Glorieta top.
7. Spot a 30 sx (170 ft) Class C cement plug from 1057 ft - 1227 ft. WOC and tag plug; reset if necessary. This will place a plug across surface casing shoe.
8. Spot a 25 sx (150 ft) Class C cement plug from 0 to 150 ft. WOC and tag plug; reset if necessary. This will leave a surface plug.
9. Remove all surface equipment and weld dry hole marker per regulations.

Wellbore schematics attached



