UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES	AND	REPORTS	ON WELLS
	•	-1-1-1-1-11	

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

NMNM67102 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NMNM131078		
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other			8. Well Name and No. PARKWAY 35 FEDERAL COM 4H			
2. Name of Operator Contact: VICKIE MARTINEZ SM ENERGY COMPANY E-Mail: VMARTINEZ@SM-ENERGY.COM			9. API Well No. 30-015-39839			
Ba. Address 6301 HOLIDAY HILL ROAD MIDLAND, TX 79707	BLDG 1 3b. P Ph: Fx: 4	hone No. (include area code 432-688-1702 BBS O 32-688-17 02BBS O	CD	10. Field and Pool, or PARKWAY;BO	Exploratory NE SPRING	
Location of Well (Footage, Sec.,	T., R., M., or Survey Description)		2015	11. County or Parish,	and State	
Sec 35 T19S R29E 450FSL	330FWL	MAY 19	รักเอ	EDDY COUNT	Y COUNTY, NM	
12. CHECK AP	PROPRIATE BOX(ES) TO INDI	ICATE NATURE CFI	OTICE, RI	EPORT, OR OTHÉ	R DATA	
TYPE OF SUBMISSION	T	ТҮРЕ О	F ACTION	<u> </u>		
□ Notice of Intent	. -	□ Deepen		on (Start/Resume)	☐ Water Shut-Off	
_		☐ Fracture Treat	□ Reclama		☐ Well Integrity	
Subsequent Report	-	☐ New Construction	□ Recomp		☐ Other	
☐ Final Abandonment Notice	· · · · · · · · · · · · · · · · ·	☐ Plug and Abandon ☐ Te		arily Abandon		
	☐ Convert to Injection	□ Plug Back	□ Water D	isposal		
3/2/2015 Set RBP at 7,552 ft	1	76 ft and calinor log she	wed casing	parted NM		
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casi 3/12/2015 RIH w/ 7 inch casi 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate	log and CBL. Found TOC at 3,67 cker and successfully tested casing and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be between 90 deg phasing) at 3,600 ft. Set on the set of the s	urred because a casing uide and screwed back connected. Attempted on 3,319 ft and 3,482 ft.	collar split. into casing to test casin	at J 4	JUN 3 2015 RECEIVED	
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casi 3/12/2015 RIH w/ 7 inch casi 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate	ng and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be betwee 90 deg phasing) at 3,600 ft. Set of true and correct.	urred because a casing uide and screwed back connected. Attempted en 3,319 ft and 3,482 ft cement retainer at 3,28	collar split. into casing to test casing Perforated 4 33 ft and brok	at 9 4 re COS	JUN 3 2015	
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casi 3/12/2015 RIH w/ 7 inch casi 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate squeeze holes (0.51?? EHD,	ng and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be betwee 90 deg phasing) at 3,600 ft. Set of true and correct. Electronic Submission #295614	urred because a casing uide and screwed back connected. Attempted en 3,319 ft and 3,482 ft cement retainer at 3,28	collar split. into casing to test casing Perforated 3 ft and brok	at 9 4 re COS	JUN 3 2015 RECEIVED	
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casi 3/12/2015 RIH w/ 7 inch casi 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate squeeze holes (0.51?? EHD,	ng and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be betwee 90 deg phasing) at 3,600 ft. Set of true and correct. Electronic Submission #295614 For SM ENERGY C	urred because a casing uide and screwed back connected. Attempted on 3,319 ft and 3,482 ft cement retainer at 3,28 verified by the BLM Wellompany, sent to the Company, sent to the Company.	collar split. into casing to test casing Perforated 3 ft and brok	at d dee COSCOP System	JUN 3 2015 RECEIVED	
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casi 3/12/2015 RIH w/7 inch casi 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate squeeze holes (0.51?? EHD, 4. I hereby certify that the foregoing Name (Printed/Typed) BRADY	ng and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be betwee 90 deg phasing) at 3,600 ft. Set of true and correct. Electronic Submission #295614 For SM ENERGY C	urred because a casing uide and screwed back connected. Attempted on 3,319 ft and 3,482 ft cement retainer at 3,28 verified by the BLM Wellompany, sent to the Company, sent to the Company.	collar split. into casing to test casing Perforated 3 ft and brok I Information arisbad	at g 4 de System	JUN 3 2015 RECEIVED	
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casi 3/12/2015 RIH w/ 7 inch casi 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate squeeze holes (0.51?? EHD,	ng and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be betwee 90 deg phasing) at 3,600 ft. Set of true and correct. Electronic Submission #295614 For SM ENERGY C	urred because a casing uide and screwed back connected. Attempted on 3,319 ft and 3,482 ft cement retainer at 3,28 verified by the BLM WellomPANY, sent to the Case Date 03/20/2	collar split. cinto casing to test casing Perforated 3 ft and broke I Information arisbad CTION ENG	at d see System SPTFD FOI	ARTESIA DISTRICT JUN 3 2015 RECEIVED Indicate Cond MOCD 6/4//	
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casi 3/12/2015 RIH w/ 7 inch casi 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate squeeze holes (0.51?? EHD,	ng and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be betwee 90 deg phasing) at 3,600 ft. Set of the strue and correct. Electronic Submission #295614 For SM ENERGY C ADAMS Submission)	urred because a casing uide and screwed back connected. Attempted on 3,319 ft and 3,482 ft cement retainer at 3,28 verified by the BLM WellomPANY, sent to the Case Date 03/20/2	collar split. cinto casing to test casing Perforated 3 ft and broke I Information arisbad CTION ENG	System SPTFD FO	ARTESIA DISTRICT JUN 3 2015 RECEIVED Indicate Cond MOCD 6/4//	
from 3,100 ft to surface. 3/11/2015 Pulled 7 inch casis 3/12/2015 RIH w/ 7 inch casis 3,436 ft. PU 30,000# over str to 500 psi but would leak off 3/13/2015 Found and isolate squeeze holes (0.51?? EHD, 4. I hereby certify that the foregoing Name (Printed/Typed) BRADY Signature (Electronic pproved By dittions of approval, if any, are attache ify that the applicant holds legal or ec ch would entitle the applicant to cond	ing and found the casing part occuring collar with 8-5/8 inch skirted gring weight to verify casing was re 350 psi in 5 min. d leak with a packer to be betwee 90 deg phasing) at 3,600 ft. Set of the	verified by the BLM WelloMPANY, sent to the Control Date 03/20/20 DERAL OR STATE Title Title Office	collar split. cinto casing to test casing Perforated 3 ft and broke Information arisbad CTION ENG OFFICE US	System SPTFD FOI MAY 14 MUSHWAS	ARTESIA DISTRICT JUN 3 2015 RECEIVED AMOCD 6/4//	

Additional data for EC transaction #295614 that would not fit on the form

32. Additional remarks, continued

circulation. 3/14/2015 Broke circulation and pumped cement job as follows: Lead slurry of 400 sx (50:50) Poz: Class C 11.8ppg + 10% Bentonite +0.4% FL-16 + 0.3% CD-35 + 5% Salt. Tail slurry of 100 sx of Class C mixed at 11.8 ppg. Circulated 18 bbls of cement to surface. 3/17/2015 Drilled out cement retainer and cement. Tested casing to 500 psi for 30 min (see chart attached-original copy delivered to Jim Amos). Pressure bled to 480 psi over 30 min. 3/18/2015 Retrieved RBP. 3/19/2015 Installed A/L equipment and returned to production.

