

NM OIL CONSERVATION

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-14
Revised August 8, 201

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

NAB1516652299

OPERATOR

☒ Initial Report ☐ Final Report

| | |
|--|--------------------------------|
| Name of Company: BOPCO, L.P. | Contact: Amy Ruth |
| Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 | Telephone No. 575-887-7329 |
| Facility Name: James Ranch Unit #012H | Facility Type: Production Well |
| Surface Owner: Federal | Mineral Owner: Federal |
| API No. 30-015-22162 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| G | 21 | 22S | 30E | 1450 | North | 1830 | East | Eddy |

Latitude 32.380677° Longitude -103.884454°

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release: Brine Water | Volume of Release: 818 bbls | Volume Recovered: 740 bbls |
| Source of Release: Jet pump on triplex unit | Date and Hour of Occurrence: 6/8/2015 Time unknown | Date and Hour of Discovery: 6/8/2015 approx. 7 am |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Heather Patterson (NMOCD) and Jim Amos (BLM) | |
| By Whom? Tony Savoie | Date and Hour: 9:34 am and 9:37 am respectively | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. (according to notification) N/A | |

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Vibration caused a bolt to shear off of the filter pot lid on the jet pump. Unit was LOTO until repairs can be made. Standing fluids were recovered from the ground and pump containments.

Describe Area Affected and Cleanup Action Taken.*

The leak affected 43,350 square feet of well pad and 880 square feet of pasture on the north side of the pad. The impacted area will be delineated and addressed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--------------------------------------|---|-----------------------------------|
| Signature: | OIL CONSERVATION DIVISION | |
| Printed Name: Amy Ruth | Approved by Environmental Specialist: | |
| Title: Assistant Remediation Foreman | Approval Date: 6/16/15 | Expiration Date: N/A |
| E-mail Address: ACRuth@basspet.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 6/10/2015 | Remediation per O.C.D. Rules & Guidelines | |
| Phone: 432-661-0571 | SUBMIT REMEDIATION PROPOSAL NO | |

Attach Additional Sheets If Necessary

LATER THAN: 7/17/15

2RP-3046