District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Azteo, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

s

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised October 10, 2003

i

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action														
					OPERA	al Report	\boxtimes	Final Repo						
and the second se							Contact CJ Summers							
Address 1017 W. Stanolind Rd, Hobbs, NM Telephone No. (575) 397-8216 Facility Name Sand Dunes 34 Federal #2 CTB Facility Type Gathering														
Surface Owner BLM Mineral Owner Lease No. API#30-015-27239													27239	
LOCATION OF RELEASE														
Unit Letter	Section	Township	Range	Feet from the	North	rth/Sonth Line Feet from the		m the	East/West Lino		County			
H	34	235	31E	2310'	 	North	66	660'		East	Eddy			
			1	Latitude N 32.20	<u>6154°</u>	Longitu	de <u>W 10</u>	3.7535	<u>2°</u>					
NATURE OF RELEASE														
Type of Release Oil							Volume of Release 140 bbls Volume Recov						ls	
Source of Release Open valve on circulating pump												Hour of Discovery		
Was Immedia	10/08/2012 @ 8:00 am If YES, To Whom?													
Yes No Not Required Mike Bratcher- OCD; James Amos- BLM														
By Whom?	Date and Hour 10/08/2012 @ 10:19 am													
Was a Waterc	If YES, Volume Impacting the Watercourse.													
16 - Thisterney			Yes 🛛					,				<u> </u>		
If a Watercoul	rse was unj	lacted, Desch	be rully.*											
Describe Cause of Problem and Remedial Action Taken.*														
The valve on the circulating pump was left open which caused 140 bbls of water to spill onto the ground. 80 bbls of water were recovered via vacuum truck. The valve was closed to prevent further leaking.														
Describe Area Affected and Cleanup Action Takes.*														
The area affected by the 140 bbls leak is approximately 70' x 40'. Remediation was completed in accordance with the remediation plan approved by NMOCD via email from Jennifer Van Curen on 12/19/2012.														
I hereby certify	, that the in	formation siv	en above	is true and comple	te io ihe	best of my k	nnwladar	and un	loreran	d that more	ant to NMC	1CD m	iles and	
regulations all	operators a	re required to	report and	Vor file certain rel	ease not	ifications and	perform	correcti	və actio	ons for relea	ases which a	may en	idanger	
	regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environn	nent. In ad-	dition, NMOC	D accepta	ance of a C-141 re	port doe	s not relieve	the opera	tor of re	sponsib	oility for co	mpliance wi	ith any	other	
federal, state, o	r local laws	and/or regel	ttions.						77777			<u>.</u>		
			and a second				OIL	JUNSI	CRVA	TIONI	<u>HVISIO</u>	N		
Signature									Ц		5			
Printed Name:	Chancey	Summers	***	oproved by D	istrict Su	pervisor	[]	nfe	n					
Title: HES Specialist Ap							6/9	15	E	piration D	ate: N	A		
E-mail Address	: Chance	y.Summers@	OXV (OP)			onditions of A		_	Λ		r			
	6-1-	-		= (575) 397-8216		aramons of A	Phinal	-1	. V		Attached			
Attach Additic								hdlb-c	<u>.</u>			$\overline{\mathbf{r}}$		
											ZK	ノー	1337	