

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1518051848 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV Big Sinks 008H (AKA PLU BS 14-25-30 1H)	Facility Type: Exploration and Production

Surface Owner:	Mineral Owner:	API No. 3001539508
----------------	----------------	--------------------

LOCATION OF RELEASE

Unit Letter N	Section 14	Township 25S	Range 30E	Feet from the 300	North/South Line	Feet from the 1980	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	----------------------	------------------	-----------------------	----------------	----------------

Latitude 32.124005 Longitude 103.853969

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 35 barrels	Volume Recovered: 30 barrels
Source of Release: 4 inch hammer union failed on charge pump	Date and Hour of Occurrence: 6-23-15 unknown	Date and Hour of Discovery 6-23-15 @ 12:08pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson via Email	
By Whom? Bradley Blevins	Date and Hour 6-24-15 @ 9:43am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 24 2015

RECEIVED



Describe Cause of Problem and Remedial Action Taken.*

A four inch hammer union failed on the charge pump releasing 35 barrels of produced water (30 barrels remained inside the lined containment). Five barrels of produced water was estimated to remain in the soil.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and was able to recover 30 barrels of produced water from the lined containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman	Approval Date: 6/29/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date: 6-24-15 Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN:

* Attach Additional Sheets If Necessary

2RP-3075