

1023 N. FRENCH DR., FLOOBS, NM 87240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1519640448		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P.		Contact: Bradley Blevins			
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329			
Facility Name: Poker Lake Unit 411H		Facility Type: Exploration and Production			
Surface Owner: Federal		Mineral Owner:		API No. 3001539930	

LOCATION OF RELEASE

Unit Letter B	Section 28	Township 24S	Range 31E	Feet from the 1000	North/South Line	Feet from the 1850	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------------	-----------------------	----------------	----------------

Latitude: 32.192796 Longitude: 103.780195

NATURE OF RELEASE

Type of Release: Crude oil, Produced water	Volume of Release: 3 barrels oil, 11 barrels produced water	Volume Recovered: 1 barrel oil, 0 produced water recovered
Source of Release: Sight glass failure	Date and Hour of Occurrence: July 2, 2015 @ 6:00pm	Date and Hour of Discovery: July 2, 2015 @ 6:28pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

If a Watercourse was Impacted, Describe Fully.\*

ARTESIA DISTRICT

JUL 10 2015

Describe Cause of Problem and Remedial Action Taken.\*

Release of oil and produced water occurred at the FWKO due to a failed sight glass. Affected well pad around production equipment, all fluid was contained within earth berm.

RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

A vacuum truck was called to the location and was able to recover 1 barrel of oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Bradley Blevins

Printed Name: Bradley Blevins

Signed By: Philip Blevins  
Approved by Environmental Specialist

Title: Assistant Remediation Foreman

Approval Date: 7/14/15

Expiration Date: NIA

E-mail Address: bblevins@basspet.com

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO

Attached ☐

Date: 7-10-15 Phone: 432-214-3704

LATER THAN: 7/14/15

\* Attach Additional Sheets If Necessary

2RP-3107