NM OIL CONSERVATION

ARTESIA DISTRICT

District 1	a .							
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210				New Mexico and Natural Resources			D15 Form C-141 Revised August 8, 2011	
District III 1000 Rio Brazos Road, Aztec, NM 87410			vation Division			Submit 1 Copy to appropriate District Office in RECEIV acordance with 19.15.29 NMAC.		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	ncis Dr., Santa Fe, NM 87505							
	I WARK A DOME IN COMMA ON COMPANY		e, NM 875	the second s			ana ang ang ang ang ang ang ang ang ang	
Release Notification and Corrective Action								
NAB1520127947			OPERA	<u>ror</u>		🛛 Initi	al Report 🛛 🗌 Final Report	
			Contact: Amy Ruth					
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Facility Name: Indian Flats Bass Federal SWD (SWD is			Telephone No. 575-887-7329 Facility Type: Exploration and Production					
located 2996 ft. SW of Well #1 API 30-015-24968)								
Surface Owner: Federal Mineral Owner:			Federal API N			APINO	0. 30-015-24968	
LOCATION OF RELEASE								
Unit Letter Section Township Range	Feet from the		South Line	Feet from the	East/\	West Line	County	
J 35 21S 28E	1652	South		2150	East		Eddy	
					I			
Latitude <u>32.434071°</u> Longitude <u>-104.055193°</u>								
NATURE OF RELEASE								
Type of Release Produced Water				Release 13 bbls			Recovered 1 bbl PW	
Source of Release Water transfer line						Date and Hour of Discovery 7/13/2015 at 8:30 am		
Was Immediate Notice Given?	If YES, To Whom?							
Yes No X Not Required N/A								
By Whom? N/A		Date and Hour N/A						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse. N/A							
If a Watercourse was Impacted, Describe Fully.*								
in a watercourse was implacied, Describe I uny.								
Describe Cause of Problem and Remedial Action Taken.*								
Surface steel water line developed a pinhole due to corrosion and produced water was released onto the well pad. The line was clamped, then isolated and repaired.								
Describe Area Affected and Cleanup Action Taken.*								
Leak affected 334 square feet of well pad within the bermed and fenced area. Vacuum truck recovered standing fluids. Impacted area was covered with								
plastic to prevent downward migration until addressed.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and								
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other								
federal, state, or local laws and/opregulations.	tance of a C-141 r	eport do	es not relieve	the operator of r	esponsil	bility for co	ompliance with any other	
	OIL CONSERVATION DIVISION							
Signature:								
Signature. / / Mug L' Mile		Approved by Environmental Byechalist /4 Brannetter						
Printed Name: Apry Ruth								
Title: Assistant Remediation Foreman		A	pproval Date	112015	E	xpiration L	Date: NH	
E-mail Address: ACRuth@basspet.com			onditions of	Annroval				
Bemediation per O.C.D. Rules & Guidelines								
Attach Additional Sheets If Necessary			ER THAN:		45		2RP-3129	

. •