Office	State of New N		Form C-103
District I - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Na	atural Resources	August 1, 2011 WELL API NO.
District II - (575) 748-1283	OIL CONSERVATIO		30-015-21147
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Fi	· · · · · · · · · · · · · · · · · · ·	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec. NM 87410	Santa Fe, NM		6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM		01000	0. State On & Gas Lease No.
87505 SUNDRY NOT (DO NOT USE THIS FORM FOR PROPC DIFFERENT RESERVOR. USE "APPLI		PLUG BACK TO A	7. Lease Name or Unit Agreement Name State
PROPOSALS.) 1. Type of Well: Oil Well 🔯	Gas Well 🔲 Óther		8. Well Number 2
2. Name of Operator		·	9. OGRID Number
COG Operating LLC 3. Address of Operator			10. Pool name or Wildcat
600 W Illinois, Midland, Texas 7	9701		Artesia; Red Lake
4. Well Location			· · · · ·
	990 feet from the S		
Section 28	Township 175 R		NMPM County Eddy
	3680 GL	, KKD, KT, OK, EK	
			,
12. Check A	ppropriate Box to Indicate	Nature of Notice,	Report or Other Data
NOTICE OF IN	TENTION TO:		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO	
TEMPORARILY ABANDON	· · · · · · · · · · · · · · · · · · ·	1	RILLING OPNS. 📋 P AND A 🛛 🕱
PULL OR ALTER CASING DOWNHOLE COMMINGLE	•	CASING/CEMEI	NT JOB
· · · —			
OTHER: 13. Describe proposed or comp of starting any proposed wo	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NM		d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or rece 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in back	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NM/ ompletion. equipment. POH w/ rods and r H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea	l pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I hole w/ mud laden erf'd csg @ 258' an % CACL @ 45' to s	
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NM/ ompletion. equipment. POH w/ rods and r H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea	l pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I hole w/ mud laden erf'd csg @ 258' an % CACL @ 45' to s	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer l spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or rece 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in back	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NM/ ompletion. equipment. POH w/ rods and r H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea	l pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s id. Welded on "Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer I spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off.
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in back cellar. Cleaned location a Spud Date:	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NMA ompletion. equipment. POH w/ rods and p H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Releas	I pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s Id. Welded on ''Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer d spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bond is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms, www.emrd.state.nm.us/ocd.
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in back cellar. Cleaned location a Spud Date:	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NMA ompletion. equipment. POH w/ rods and p H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Releas	I pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s Id. Welded on ''Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer d spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bond is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms, www.emrd.state.nm.us/ocd.
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or rece 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in back cellar. Cleaned location a Spud Date:	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NMA ompletion. equipment. POH w/ rods and r H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Release above is true and complete to the	I pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s Id. Welded on ''Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer d spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bond is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms, www.emrd.state.nm.us/ocd.
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing, would not 07/13/15 Tagged plug @ 07/14/15 Moved in back cellar. Cleaned location a Spud Date: hereby certify that the information IGNATURE Area Month	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NMA ompletion. equipment. POH w/ rods and p H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Release above is true and complete to the TITLE	l pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s id. Welded on "Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer 1 spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bond is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms. www.mnrd.state.nm.us/ocd. parte
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing, would not 07/13/15 Tagged plug @ 07/14/15 Moved in back cellar. Cleaned location a Spud Date: hereby certify that the information IGNATURE Are Month	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NMA ompletion. equipment. POH w/ rods and p H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Release above is true and complete to the TITLE	l pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s id. Welded on "Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer 1 spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bond is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms. www.mnrd.state.nm.us/ocd. parte
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in back cellar. Cleaned location a Spud Date: hereby certify that the information IGNATURE Account of the second ype or print name Bood Month or State Use Only PPROVED BY:	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NMA ompletion. equipment. POH w/ rods and p H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Release above is true and complete to the TITLE	l pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s id. Welded on "Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer d spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bend is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms. www.gmnrd.state.nm.us/ocd. ge and belief.
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in backling cellar. Cleaned location and Spud Date: hereby certify that the information IGNATURE Area Month or State Use Only	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NMA ompletion. equipment. POH w/ rods and r H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Release above is true and complete to the TITLE	l pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s id. Welded on "Abo	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer 1 spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bond is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms. www.emrd.state.nm.us/ocd. DATE 7-15-15
OTHER: 13. Describe proposed or compl of starting any proposed wo proposed completion or reco 07/09/15 MIRU plugging surface. POH w/ tbg. RII 673'. Loaded hole w/ mu (per Randy Dade). WOO to test casing. would not 07/13/15 Tagged plug @ 07/14/15 Moved in back cellar. Cleaned location a Spud Date: hereby certify that the information IGNATURE And Month or State Use Only PPROVED BY:	eted operations. (Clearly state al rk). SEE RULE 19.15.7.14 NM/ ompletion. equipment. POH w/ rods and r H w/ workstring. Spotted 15 sx d laden fluid. Did not circulate. C. Tagged plug @ 439'. Loaded go past 60'. Per Randy Dade, P 45'. Spotted 15 sx cement w/ 2 hoe and welder. Cut off wellhea and moved off. Rig Release above is true and complete to the TITLE	I pertinent details, an AC. For Multiple Co pump. Dug out cella cement w 2 % CAC Pumped 1 sack of I I hole w/ mud laden erf'd csg @ 258' and % CACL @ 45' to s ad. Welded on "Abo se Date: best of my knowledg Age_t	mpletions: Attach wellbore diagram of r. Picked up on tbg and 4 1/2 csg parted at L @ 730'. WOC. 07/10/15 Tagged plug @ LCM, 15 sx cement w/ 2 % CACL @ 673'; fluid. Did Not Circulate. Picked up packer 1 spotted 35 sx cement @ 258. WOC. surface. Rigged down and moved off. ve Ground Dry Hole Marker''. Backfilled Approved for plugging of well bore only Liability under bond is retained pendin of C-103 (Subsequent Report of Well Pl which may be found at OCD Web Page Forms. www.emrd.state.nm.us/ocd. DATE 7-15-15

.