Submit 1 Copy To Appropriate District	State of New Mexico	BLM ROW NM65392 Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		30-015-25665
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Compromise SWD
		8. Well Number
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD		
1. Type of Well: Oil Well 2. Name of Operator	Gas wen Outer SwD	9. OGRID Number
Yates Petroleum Corporation	· ·	025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia, N	M 88210	SWD; Upper Penn
4. Well Location	<u> </u>	
	1980 feet from the <u>North</u> line and	800 feet from the <u>East</u> line
Section 30	Township 18S Range 27E	NMPM Eddy County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3,281' GR	
	· · · ·	
12. Check A	Appropriate Box to Indicate Nature of Notice	, Report or Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PAND A		
CLOSED-LOOP SYSTEM		
	n an MIT 🛛 🛛 OTHER:	Г
	leted operations. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
	rk): SEE RULE 19.15.7.14 NMAC. For Multiple Co	
proposed completion or reco	ompletion.	
Yates Petroleum Corporation plans to		
	for a casing integrity test. If the test is good, give O	CD a 24 hour notice that we will be performing
a casing integrity test and re		· · · · · · · · · · · · · · · · · · ·
	MIT MIRU WSU. NU BOP. RU all H2S safety equ tubing hydro testing the tubing as it is pulled, if the tu	
	Test the annulus to 500 psi if it holds notify the OC	
service.	Test the annulus to 500 psr fr it holds notify the Och	b and full all official with and fetulli the well to
	lem then TIH with 2.875" work string, packer and RB	BP to find and isolate leaks.
	<u>CONTIN</u>	UED ON NEXT PAGE:
· · · · · ·	· · ·	
	·	
Spud Date:	Rig Release Date:	
· · · · · · · · · · · · · · · · · · ·		
		and a second
I-hereby certify that the information a	above is true and complete to the best of my knowled	ge and belief. and the particular of the
CLOSED-LCCP1 (STEA)	no w (c. 1920) 1999 - Oli (c. 1920) 1999 - Oli (c. 1990)	
SIGNATURE OF THE	Matta TITLE Regulatory Reporting	Technician DATE July 10 2015
Silling Courter	ITTLE Regulatory Reporting	Technician DATE July 10, 2015
Type or print name Laura Wa	atts E-mail address: <u>laura@yatespetrole</u>	um.com PHONE: <u>575-748-4272</u>
For State Use Only		
	cha Di-HN M	NUM n/m -
APPROVED BY: 1700	U TITLE DT TOP	W/SV DATE ///6/2015
Conditions of Approval (if any):		
A OCD MUST /	Witness MIT EST BEE	In 1: 1: Augli
	WITTERS MILI LEST Der	JOLL IN CCTTOM CANICOMMENCE

Form C-103 continued:

- 5. Once the leaks have been isolated, set CIBP and cement retainer via WL. Pump the recommended squeeze job and WOC at least 24 hours. If a positive squeeze pressure cannot be obtained over flush and re-squeeze.
- 6. Drill out the cement retainer and CIBP. Pressure test the squeezed interval, if interval will not pressure test re-squeeze the interval.
- 7. Repeat steps 4, 5 and 6 until all of the detected leaks have been repaired.
- 8. Hydrotest the nickel plated or coated packer and plastic coated 2.875" tubing back in the hole. Set the packer at +/- 7,947'.
- 9. ND BOP and NU wellhead load the annulus with 126 bbls of packer fluid containing an oxygen scavenger and biocide. Pressure
- test the annulus for 10 minutes at 1000 psig. Give the OCD a 24 hour notice that we will be performing a casing integrity test.
- 10. Turn well over to production.

Schematic attached

Regulatory Reporting Technician

