

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520958553

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC <i>217955</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: LOVING FALCON 28 #001H	Facility Type: Battery

Surface Owner: Fee	Mineral Owner:	API No. 30-015-37000
--------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 28	Township 23S	Range 28E	Feet from the 1980'	North/South Line North	Feet from the 530'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.2779961 Longitude -104.0855331

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 100 bbls PW	Volume Recovered: 95 bbls PW
Source of Release: Tank	Date and Hour of Occurrence: 7/8/2015 5:00 am	Date and Hour of Discovery: 7/8/2015 5:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Fri 7/10/2015 3:01 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION
ARTESIA DISTRICT**

JUL 28 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a plumbing failure that sent gas to the water tank, over pressurizing the tank and causing the fiber glass tank to fail at the bottom seam. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. The tank was replaced and the facility cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>7/28/15</i>	Expiration Date: <i>NIA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: July 22, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

220-3171