

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1521257588 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 2100787	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: JRU-10	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-23075

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	1	23S	30E	1980	North	660	East	Eddy

Latitude N 32.335568° Longitude W 103.827592°

NATURE OF RELEASE

Type of Release: Produced water and condensate	Volume of Release: 50 bbls. PW and 5 bbls. condensate	Volume Recovered: 13 bbls. PW and 2 bbls. condensate
Source of Release: Produced water tank	Date and Hour of Occurrence: 7/29/15, time unknown	Date and Hour of Discovery: 7/29/15 at approximately 8:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, and Jim Amos	
By Whom? Tony Savoie	Date and Hour 7/29/15, first attempt at 1:51 p.m. confirmed at 6:14 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 30 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A coupling on the water transfer pump failed causing the tank to overflow. The coupling was replaced the day of the release.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted about 1000 sq.ft. inside the earthen containment around the Oil and PW tanks. All of the free standing fluid was recovered with a vacuum truck.
The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Tony Savoie</u>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Waste Management and Remediation Specialist		Approval Date: <u>7/31/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>tasavoie@basspet.com</u>		Conditions of Approval:	
Date: <u>7/30/15</u> Phone: 432-556-8730		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

MITIGATION per O.C.D. Rules & Guidelines
MITIGATION PROPOSAL NO.
DATE: 7/31/15
ATER THAN:

2RP-3179