## Form 3160-5 (March 2012)

# NM OIL CONSERVATION

ARTESIA DISTANTIED STATES
DERARTMENT OF THE INTERIOR
THERE IN ZHEN AND MANAGEMENT

NMOCD


FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

ე <mark>p</mark> .િ!	RAUZUIDLAND MANAGEM	IENT	5. Lease Serial N	lo.
Do not use this	NOTICES AND REPORTS ( FET MED proposals to drill Use Form 3160-3 (APD) fo	ON WELLS or to re-enter a	6. If Indian, Allo	NM 12557 ottee or Tribe Name N/A
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA	'Agreement, Name and/or No.
1. Type of Well				N/A
✓ Oil Well ☐ Gas Well ☐ Other			8. Well Name an	d No. DUNCAN FEDERAL #11
2, Name of Operator  JALAP	ENO CORPORATION		9. API Well No.	30-005-64211
	X 1608 RQUE, NM 87103 505-243	nc No. <i>(include area c</i> 2-2050	ode) 10. Field and Po	ol or Exploratory Area WILDCAT, SAN ANDRES
4. Location of Well (Footage, Sec., T.	• • •		11. County or Pa	rish, State CHAVES COUNTY, NM
	660' FSL & 990' FWL SEC. 7, T-9S			
12. CHE	CK THE APPROPRIATE BOX(ES) TO	O INDICATE NATUR	E OF NOTICE, REPORT OR	OTHER DATA
TYPE OF SUBMISSION		T	YPE OF ACTION	
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production (Start/Resur	me) Water Shut-Off Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice		Piug and Abandon Plug Back	☐ Temporarily Abandon ☐ Water Disposal	
1. CEMENT FROM 2147' 2. FILL HOLE WITH GEL I 3. CEMENT FROM 1700' 4. FILL HOLE WITH GEL I 5. CEMENT FROM 530' T	3 = = :	HOC & Tagg ex wocata	o: 20r Above 214 g@Or Above 1.	71. 500°
7. SET DRY HOLE MARK	D DRY. ER. NM OIL CONSERVATIO ARTESIA DISTRICT	ON APPRO	OVED FOR 3_M	ONTH PERIOD
Accepted for record	JUL 3, 0 2015	ENDR	G <u>OCT 27 2015</u>	- The state of the
(0) 1	RECEIVED			
14. I hereby certify that the foregoing is t	rue and correct. Name (Printed/Typed)			
H. Emmons Yates, III		Title Vio	e President	
Signature A. Com		Date 07/20/2	015	
	THIS SPACE FOR F	EDERAL OR ST	ATE OFFICE USE	
Approved by /S/DAV	ID R. GLASS	PETF	OLEUM ENGI <b>NEER</b>	" " " JUL 2 7 2015
Conditions of approval, if any, are attached that the applicant holds legal or equitable to	d. Approval of this notice does not warra	int or certify	ROSWELL FI	Date


Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

SCHEMATIC PRIOR TO PLUG AND ABANDON
JALAPENO CORPORATION
DUNCAN FEDERAL #11
CHAVES COUNTY, NEW MEXICO
API NO. 30-005-64211



# SCHEMATIC AFTER PLUG AND ABANDON JALAPENO CORPORATION DUNCAN FEDERAL #11 CHAVES COUNTY, NEW MEXICO API NO. 30-005-64211



### BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 627-0272

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90<sup>th</sup> day provide the BLM Roswell Field Office (RFO), prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action. Unless the well has been properly plugged, the rig shall not be removed from over the hole without prior approval.
- 2. <u>Notification</u>: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.