Office District I = (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II = (575) 748-1283 811 S. First St., Artesia, NM 88210			Obs. 1 - 12 2000		
District II - (575) 748-1283	Energy, Minerals and Natural Re	esources	October 13, 2009		
			WELL API NO. 30-015-24429		
	OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
District III - (505) 334-6178	1220 South St. Francis I	Dr.	STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV = (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM	•		o, but on a gur bijor i e		
87505	CAND DEPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
SUNDRY NOTICE: (DO NOT USE THIS FORM FOR PROPOSAL	S AND REPORTS ON WELLS S TO DRILL OR TO DEEPEN OR PLUG BA	CK TO A	Loving 1 State		
DIFFERENT RESERVOIR. USE "APPLICAT			Loving 1 State		
PROPOSALS.)			8. Well Number 2		
1. Type of Well: Oil Well Gas Well Other			9. OGRID Number		
2. Name of Operator COG Operating LLC			9. OGRID Number		
3. Address of Operator			10. Pool name or Wildcat		
600 W. Illinois, Midland, TX 79701			Black River Morrow		
4. Well Location		<u></u>			
i '	50 fait from the S	line and 60	feet from the W line		
Section 6	Township 24S Range 28		MPM County Eddy		
	1. Elevation (Show whether DR, RKB 128 GR	, KI, GK, etc.)	1. The Control of the		
	Andrew An	<u>, , , , , , , , , , , , , , , , , , , </u>			
10 Charle Aire	propriate Box to Indicate Nature		Danam an Ostatate nm. ús		
12. Check App	propriate Box to indicate Nature	e of Notice,	Report of mid. state.nm.us www.emmrd.state.nm.us www.emmrd.state.nm.us rent forms are available on our rent forms are available when beire and should be used when		
NOTICE OF INTE	ENTION TO:		www.emnra www.e		
· ·		MEDIA CUT	rent lo. should be unents.		
		MMEN Me	bsite and latory documents		
		SING/C	tent forms and should be used to be being and should be used to be being filing regulatory documents.		
DOWNHOLE COMMINGLE	·				
		i,			
ÖTHER:		IER:	<u> </u>		
13. Describe proposed or complete	ed operations. (Clearly state all pertin	ent details, and	I give pertinent dates, including estimated da		
of starting any proposed work) proposed completion or recom). SEE RULE 19.15.7.14 NMAC. Fo	r Multiple Con	npletions: AMCPUEIGONSEPMATION ARTESIA DISTRICT		
1. MIRU plugging equipmen					
2. Set CIBP @ 6000. Circula			AUG 1 2 2015		
3. Spot 20 sx cement @ 6000-					
4. Cut and POH 4 1/2 csg (+/			RECEIVED		
5. Cut and POH 7' esg.			كينا بين لا يان مس الله الله الله الله الله الله الله الل		
	ag (BTM salt, stub, shoe plug)		<u> </u>		
7.Spot 65 sx of cement @ 610	0-500. Tag (top of salt, shoe)	• •	Approved for plugging of well bore only. Liability under bond is retained pending rece		
8. Spot 45 sx @ 100-surface,	J. and Thomas IX-1 a Williams		of C-103 (Subsequent Report of Well Pluggin		
9. Cutt off wellhead and welc	d on Dry Hole Marker.		which may be found at OCD Web Page under		
			Forms, www.cmnrd.state.nm.us/ocd.		
n in	Rig Release Date:				
Spud Date:					
004	Oliver or and by Q=1	1 - 10111 -			
vell bac must be	plugged by 8-1				
vell bac must be			e and belief.		
vell bac must be			e and belief.		
I hereby certify that the information abo	ove is true and complete to the best of	my knowledge			
I hereby certify that the information abo	ove is true and complete to the best of	my knowledge	DATE 8-11-75		
I hereby certify that the information about	ove is true and complete to the best of	my knowledge	DATE 8-11-75		
I hereby certify that the information about SIGNATURE But Type or print name Bear Monty	ove is true and complete to the best of	my knowledge			
I hereby certify that the information about SIGNATURE But Type or print name Bear Monty	ove is true and complete to the best of	my knowledge	DATE 8-11-15		
I hereby certify that the information about SIGNATURE But Months Type or print name But Months For State Use Only APPROVED BY:	ove is true and complete to the best of	my knowledge	DATE 8-11-75		
I hereby certify that the information about SIGNATURE Type or print name Bear Months For State Use Only APPROVED BY: Conditions of Approval (if any):	ove is true and complete to the best of	my knowledge	DATE 8-11-15		
I hereby certify that the information about SIGNATURE Type or print name Bear Months For State Use Only APPROVED BY: Conditions of Approval (if any):	TITLE A Service and complete to the best of the best o	my knowledge	DATE 8-12-15 ASSOCIATE DATE 8-12-15 DATE 8-12-10-2015		
Spud Date: well be must be I hereby certify that the information about SIGNATURE Type or print name For State Use Only APPROVED BY: Conditions of Approval (if any): See Attache of	TITLE A Service and complete to the best of the best o	my knowledge	DATE 8-11-15		

UNY UPOLICE HIM LIN 13-3/8 @ 556 Lovina 1 State 2 WI 30-015-24429 Yat 32. 2423477 Long -104, 1459274 9-5/8"@ 2255 TOC 25501 Perfs @ 6022-6120: = Perfs@ 6432-6582' = Perfs @ 6920-7097' = Perfs @ 7562 - 7710' # Perfs @ 8270-8336' Perfs @ 8858 - 9146' CIBP@ 9520' (12/14/2011) CIBP@ 10212' w/35'cmt on top (09/14/2011 TOC @ 10220' CIBP@ 10260' W/35' TOL@ 10228' 10,310-10,330 (2 spt) 10,362-10,366 (2 spf) 10,392-10,394 (2spt) set@ 10,2601 w/ 35" cmt on top (08/16/20) CIBP@12,175 w/35 cmt on top (07/31/2007) = Penfs @ 12,231-12,243 = Perfs@12,316-12,4301 CIBP @ 12,530 (6/16/2006) Perts @-12,658-12,662' Perfs @ 12,676-12,680'
Perfs @ 12,688-12,692' 6 4-1/2" set @ 12,840'

TD 12,8401

454 C 100-30-198-13-3/8 @556 Lovina 1 State 2 610 - 500 65.5 € API 30-015-24429 Top of Salt, shoe Lat 32.2423479 Long -104.1459,274 5554C 2300-2200 TAS BTM salt, stud, stee play 9-56"@ 2255" Toc 2550' CIAPE 6000 W/ 2004 Perfs @ 6022-6120 Perfs@ 6432-6582' Perfs @ 6920-70971 Perfs @ 7562 - 7710' Perfs @ 8270-8336' @ 9498 W/ 5805* Perfs @ 8858 - 9146' TOC 2550 CIBP@ 9520 (12/14/2011) CIBP@ 10212' 41/35'cmt on top (09/14/20) TOC @ 102201 CIBP@ 10260' W/35' TOL@ 10228' 10,310-10,330' (2 spf) 10,362-10,366 (2 spf) 10,392-10,394' (2spf) set@ 10,260' w/35' cmt antop (08/16/20 CIBP@12,175'w/35 cmt on top (07/31/2007) = Perfs @ 12,231-12,243' = Perfs@12,316-12,430' CIBP @ 12,530 (6/16/2006) Perfs @ 12,658-12,662' Perfs @ 12,676-12,680' Perfs @ 12,688-12,6921 4-1/2" set @ 12,840' 12,8401 TD

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:_	COG				
- Well Name	& Number:	Lou	195	tates	7 2
API #:	<i>3</i> 0-	015	124	429	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

8/12/2015

11. Minimum WOC time for tag plugs will be 4 Hrs.

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50° below and 50° above).