Submit 1 Copy To Appropriate District Office	Form C-103
Submit 1 Copy To Appropriate District Office NM OIL CONSERVATION State of New Mexico District I- (575) 393-6161 ARTESIA DISTRICT TO Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II- (575) 748-1283 AUC.  T. 2045 V. GONGED VA. THOM DIVISION DIVISION.	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240	30-015-42107
District II- (575) 748-1283 ALL 5 205IL CONSERVATION DIVISION  1301 W. Grand Ave., Artesia, NM 88240  1302 G. 41 St. Francis D.	5. Indicate Type of Lease
District III- (505) 334-6178 1 000 Rio Brazos Rd., Aztec, NM 8741 0 220 South St. Francis Dr.	STATE STEE
District IV- (505) 476-3460 <b>RECEIVED</b> Santa Fe, NM 87505 87505	6. State Oil & Gas Lease No.
87505	VO-8933
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Chip State
PROPOSALS.) 1. Type of Well: Oil Well  Gas Well  Other	8. Well Number 2
1. Type of Well: Oil Well Gas Well Other  2. Name of Operator	9. OGRID Number
Mack Energy Corporation	013837
3. Address of Operator	10. Pool Name or Wildcat .
P.O. Box 960 Artesia, NM 88210	Wildcat Glorieta-Yeso
4. Well Location	2015 a a
Unit Letter G 1980 feet from the North line and Section 32 Township 23S Range 23E	2015 feet from the East line
Section 32 Township 23 S Range 23 E  11. Elevation (Show whether DR, RKB, RT, GR etc.)	NMPM County Eddy
4332' GR	
A STATE OF THE STA	The state of the s
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
	•
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK REMEDIAL WORK	SEQUENT REPORT OF:  K
TEMPORARILY ABANDON 🔀 CHANGE PLANS 🔲 COMMENCE DR	<u> </u>
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	<del></del>
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER:	· · · · · · · · · · · · · · · · · · ·
	d give portional datas including estimated data
13. Describe proposed or completed operations. (Clearly state all pertinent details, an	
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion	as: Attach wellbore diagram of proposed completion
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion or recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol	as: Attach wellbore diagram of proposed completion lows:
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing	as: Attach wellbore diagram of proposed completion lows:
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion or recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap.	as: Attach wellbore diagram of proposed completion lows: tus may be granted after a ssful MIT test is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion OF recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test.	as: Attach wellbore diagram of proposed completion lows: tus may be granted after a ssful MIT test is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion OF recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid.  4. Contact OCD to witness pressure test.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a ssful MIT test is performed.  It is performed.  It is performed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.  Spud Date:  Rig Release Date:	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a saful MIT test is performed. ct the OCD to schedule the test may be witnessed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a saful MIT test is performed. ct the OCD to schedule the test may be witnessed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.  Spud Date:  Rig Release Date:	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a saful MIT test is performed. ct the OCD to schedule the test may be witnessed.
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion Operecompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.  Spud Date:  Rig Release Date:  I hereby certify that the information above is true slid complete to the best of my knowledge.	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a significant state of the order of
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion OF-recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.  Spud Date:  Rig Release Date:  I hereby certify that the information above is true slid complete to the best of my knowledge SIGNATURE TITLE Production Clerk	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a significant state of the oct to schedule the test may be witnessed.  DATE 8/4/15
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of Recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.  Spud Date:  Rig Release Date:  I hereby certify that the information above is true slid complete to the best of my knowledge SIGNATURE	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a significant street is performed. It is performed. It is performed in the OCD to schedule the test may be witnessed.  DATE 8/4/15
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion OF-recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.  Spud Date:  Rig Release Date:  I hereby certify that the information above is true slid complete to the best of my knowledge SIGNATURE TITLE Production Clerk	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a significant state of the OCD to schedule the test may be witnessed.  DATE 8/4/15
13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion of Recompletion.  Mack Energy Corporation proposes to Temporarily Abandon the Chip State #2 as fol 1. POH w/rods and tubing 2. Place CIBP @ 3831' w/35' cement cap, CIBP @ 1997' w/35' cement cap. 3. Circulate hole w/packer fluid. 4. Contact OCD to witness pressure test. 5. Test well to 500# for 30 minutes, w/chart.  Spud Date:  Rig Release Date:  I hereby certify that the information above is true slid complete to the best of my knowledge SIGNATURE	is: Attach wellbore diagram of proposed completion lows:  It was may be granted after a significant street is performed. It is performed. It is performed in the OCD to schedule the test may be witnessed.  It was may be granted after a significant street in the occupancy of the occupancy occu

## **Mack Energy Corporation**

Chip State #2 Sec. 32 T23S R23E 30-015-42107


Before 13 3/8 casing @ 451' cmt w/500sx, circ. 9 5/8 casing @ 2022' cmt w/1200sx, circ. Perfs from 2047-21961 CIBP @ 6650'w/35'cmt cap Perfs from 6724-6947' 7" casing @ 7145'

cmt w/990sx, TOC @

1570'

TD @ 7145'

After
Circ. hole with packer fluid and test to 500#for 30 min.



· C