| Submit I Copy To Appropriate District Office | State of New Mexico | Form C-103 |
|--|---|--|
| (***/****************** | Energy, Minerals and Natural Resources | Revised July 18, 2013 WELL API NO. |
| 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 | | 30-015-10472 |
| 811 S. First St., Artesia, NM 88210 | OIL CONSERVATION DIVISION | 5. Indicate Type of Lease |
| <u>District III</u> ~ (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 | 1220 South St. Francis Dr. | STATE FEE X |
| <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| | ND REPORTS ON WELLS O DRILL OR TO DEEPEN OR PLUG BACK TO A FOR PERMIT" (FORM C-101) FOR SUCH | 7. Lease Name or Unit Agreement Name Brainard |
| PROPOSALS.) | /ell X Other Injection | 8. Well Number ₀₀₇ |
| Name of Operator Tandem Energy Corporation | | 9. OGRID Number |
| 3. Address of Operator | | 10. Pool name or Wildcat |
| 2700 Post Oak Blvd. Ste. 1000, Houston, TX 77056 | | Turkey Track |
| 4. Well Location | | Turkey flack |
| Unit Letter Lot 3 : 5 | feet from the South line and 132 | 25 feet from the West line |
| Section 34 | Township 18S Range 29E | NMPM County Eddy |
| | Elevation (Show whether DR, RKB, RT, GR, etc.) | |
| | 3433 GR | |
| 12. Check Appro | priate Box to Indicate Nature of Notice, | Report or Other Data |
| NOTICE OF INTEN | TION TO: SUB | SEQUENT REPORT OF: |
| | G AND ABANDON ☐ REMEDIAL WOR | |
| TEMPORARILY ABANDON 🔲 CHA | NGE PLANS 🔲 COMMENCE DRI | LLING OPNS. ☐ P AND A ☐ |
| PULL OR ALTER CASING MUL | TIPLE COMPL ☐ CASING/CEMEN | T JOB 🗔 |
| DOWNHOLE COMMINGLE | | |
| CLOSED-LOOP SYSTEM | C OTUER | |
| OTHER: | perations. (Clearly state all pertinent details, and | d give pertinent dates, including estimated date |
| | EE RULE 19.15.7.14 NMAC. For Multiple Cor | |
| proposed completion or recomplet | | |
| Pressured up on annulus to 500 psi. Lost all press Removed tubing and packer. | ure in 10 minutes. | |
| Using a Retrievable Bridge Plug and tension set p | acker, the leak was identified between 174' to 186'. | |
| A Casing collar and single shot perforating gun wa | ere performed and were unsuccessful. The cement plug was drilled out, is run to identify the hole in casing. The hole was found on a collar conn | |
| | vas pumped. Cement was circulated back to surface in the conductor ca | |
| ons. The 7" casing valve was repaired, and the cement | g valve was closed to squeeze the cement. The casing valve had a leak plug and repair was tested. The pressure bled off. | t. The well was shut-in to wait on cement. |
| at 136'. cker and tubing. | | NM OIL CONSERVATIO |
| ore and assig. | | AUG 2.4 2015 |
| | | DECEIVED |
| Spud Date: | Rig Release Date: | RECEIVED |
| Spud Date. | Nig Nelease Date. | |
| | | |
| I hereby certify that the information above | is true and complete to the best of my knowledge | e and belief. |
| \bigcap | | |
| SIGNATURE X. LOCAL | TITLE Regulatory Specialist | DATE 08/11/2015 |
| Type or print name L. Kiki Lockett | E-mail address: kikil@t5energy.com | PHONE:713-987-7326 |
| For State Use Only | N. A.S. m | 1.1/4 |
| APPROVED BY:(if any): | TITLE DISTIN | 0131\ DATE 1/3/13 |