## **NM OIL CONSERVATION** ARTESIA DISTRICT

Form 3160-5 (March 2012)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

AUG 3 1 2015 OCD Artesia

FORM APPROVED

**BUREAU OF LAND MANAGEMENT** 

	OMB No. 1004-01	137
	Expires: October 31	, 20
5. Lease Serial No.		

	DECEN (FD	NM- 59385		
SUNDRY NOTICES AND REPORTS  Do not use this form for proposals to dril	6. If Indian, Allottee or	6. If Indian, Allottee or Tribe Name		
abandoned well. Use Form 3160-3 (APD) f				٠.
SUBMIT IN TRIPLICATE – Other instruc	7. If Unit of CA/Agree	7. If Unit of CA/Agreement, Name and/or No.		
Type of Well	,	8. Well Name and No.		
2. Name of Operator		H.B. 3 Federal #1		
Unit Petroleum	one No. (include area code)	9. API Well No. 30-015-25766		
PO Box 702500 Tulsa, Ok 74170-2500		10. Field and Pool or Exploratory Area Cedar Canyon		
	93-7700	11. County or Parish, S	State	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1980 FSL & 1980 FEL, Section 3, T24S- R29E		Eddy, N.M.	· · · · · · · · · · · · · · · · · · ·	
12. CHECK THE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF N	OTICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF	ACTION		
Notice of Intent	Deepen 🗸	Production (Start/Resume)	Water Shut-Off	
Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	New Construction	Recomplete	Other	-
Change Plans	_ · _	Temporarily Abandon	o(5√)	
Final Abandonment Notice Convert to Injection  13. Describe Proposed or Completed Operation: Clearly state all pertinent of		Water Disposal	, , , , , , , , , , , , , , , , , , ,	
following completion of the involved operations. If the operation resu testing has been completed. Final Abandonment Notices must be filed determined that the site is ready for final inspection.)  Anticipated Start Date 5/1/2015  1. Pull test anchors and MIRU well service unit.  2. Clean up around wellhead  3. NU BOP w/ 2 7/8" pipe rams and POOH w/tbg.  4. Possible bridge from csg leak.  5. TIH w/ 7" 10k RBP and spot sand & pkr.  6. SET RBP at 5,500' and test at 500 psi.  7. Move packer up the hole +/- 500 ft at a time and test casing. Last	only after all requirements, inclu	iding reclamation, have been Accepte	9/3/15  d for record  MOCD	
<ol> <li>If leak is detected, set test pkr, need to get injection rate. Release</li> <li>TIH with cement retainer, load and test csg.</li> <li>MIRU cement truck, pump sufficient amount to repair leak. WOC</li> <li>PU BHA, TIH tag cmt PU power swivel. Drill out squeeze.</li> <li>LD BHA &amp; PS. Release all rental equipment. Rod up and move</li> <li>Clean location &amp; return well to production.</li> </ol>	,	SEE ATTACHEI CONDITIONS (	D FOR OF APPROVAL	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed				
Abel Resendez	Title Engline	Ur		<u>·</u>
Signature CSet 2	Date 4/1	/IS ACC	CEPTED FOR REC	OR
THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		1
Approved by Charles Nimmer	DETONI EIIRA ENGI	MEED	AUG 2 7 2015	T

entitle the applicant to conduct operations thereon. CARLSBAD FIELD OFFICE Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

H.B. 3 Federal #1 30-015-25766 Unit Petroleum August 26, 2015 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by November 26, 2015.

- 1. The CIT is to be performed on the production casing according to Onshore Oil and Gas Order No. 2, III.B.1.h. Submit results to BLM. Notify BLM if test fails.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Surface disturbance beyond the originally approved pad must have prior approval.
- 4. Closed loop system required.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. Operator to have H2S monitoring equipment on location.
- 7. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 8. Subsequent sundry required detailing work done and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 9. See attached for general requirements.

CLN 082615