

# NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico

Energy Minerals and Natural Resources

SEP 15 2015

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr. Hobbs, NM 88240  
District II  
811 S. First St. Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr. Santa Fe, NM 87505

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
Submit Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

**NAB 152-6426751** **4323**

<b>OPERATOR</b>		<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: Chevron USA Inc.		Contact: Stephen Gwin	
Address: 1616 W Bender Blvd, Hobbs NM		Telephone No.: 575-263-0427	
Facility Name: Federal BN #1		Facility Type: Gas Well Compressor	
Surface Owner: Federal		Mineral Owner: Federal	
		API No.: 30-015-23498	

## LOCATION OF RELEASE

Unit Letter H	Section 17	Township 22S	Range 26E	1592 Feet from the	North/South Line North Line	444 Feet from the	East/West Line East Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	--------------------------------	----------------------	-----------------------------	----------------

Latitude 32.395141 Longitude -104.307896

## NATURE OF RELEASE



Type of Release: Vent	Volume of Release: 110 mcf	Volume Recovered: 0
Source of Release: Suction nipple on compressor	Date and Hour of Occurrence: 9/12/2015 ~ 1:00 PM to 9/14/2015 ~ 8:00 AM	Date and Hour of Discovery: 9/14/2015 8:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Stephen Gwin	Date and Hour: 9/15/2015 12:25 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. \*

Describe Cause of Problem and Remedial Action Taken. \*  
Crack was discovered on nipple on the suction side of compressor.

Describe Area Affected and Cleanup Action Taken. \*  
Nipple on suction side of compressor was replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Stephen Gwin		Signed By:  Approved by Environmental Specialist:	
Title: HES Specialist		Approval Date: 9/21/15	Expiration Date: N/A
E-mail Address: Stephen.gwin@chevron.com		Conditions of Approval: <b>FINAL</b>	
Date: 9/15/2015 Phone: 575-263-0427		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-32646