

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526056410 OPERATOR ☒ Initial Report ☐ Final Report

| | | |
|---|---|----------------------|
| Name of Company: BOPCO, L.P. <u>2140137</u> | Contact: Amy Ruth | |
| Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 | Telephone No. 575-887-7329 | |
| Facility Name: Indian Flats Bass Federal #1 Tank Battery (located 2996 ft. SW of Well #1 API 30-015-24968) | Facility Type: Exploration and Production | |
| Surface Owner: Federal | Mineral Owner: Federal | API No. 30-015-24968 |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| J | 35 | 21S | 38E | | | | | Eddy |

Latitude 32.43400° Longitude -104.05580°

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Produced Water | Volume of Release 7 bbls | Volume Recovered 2 bbls |
| Source of Release 2" fitting on line | Date and Hour of Occurrence 9/3/2015 time unknown | Date and Hour of Discovery 9/3/2015 time unknown |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? N/A | |
| By Whom? N/A | Date and Hour N/A | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. N/A | |

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.*
A 2" fitting failed on the line going from the heater treater to the produced water tanks.

SEP 14 2015

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
The leak affected 650 square feet of caliche pad within the area of the earthen containment. Standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--------------------------------------|--|--|-----------------------------|
| Signature: <u>Amy Ruth</u> | | OIL CONSERVATION DIVISION | |
| Printed Name: Amy Ruth | | Approved by Environmental Specialist: <u>[Signature]</u> | |
| Title: Assistant Remediation Foreman | | Approval Date: <u>9/17/15</u> | Expiration Date: <u>N/A</u> |
| E-mail Address: ACRuth@basspet.com | | Conditions of Approval: | |
| Date: 9/14/2015 Phone: 432-661-0571 | | Remediation per O.C.D. Rules & Guidelines | |

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/22/15

2RP-3260