

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 22 2015

Form C-141
Revised August 8, 2011

Submit a copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

nAB1526657039

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 153	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 3001531412
------------------------	------------------------	--------------------

LOCATION OF RELEASE

Unit Letter G	Section 6	Township 24s	Range 30E	Feet from the 1830	<u>North</u> /South Line	Feet from the 1980	<u>East</u> /West Line	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	--------------------------	-----------------------	------------------------	----------------

Latitude: 32.248582 Longitude: 103.918065

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 barrels	Volume Recovered: 5 barrels
Source of Release: Swedge on produced water tank	Date and Hour of Occurrence: 9-18-15 @ 1:00pm	Date and Hour of Discovery: 9-18-15 @ 1:30pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

BOPCO EHS was notified of a spill that occurred when a pin hole developed in the swedge of the produced water tank load line. A vacuum truck was called to the location and recovered 5 barrels from within the earth berm.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and was able to recover 5 barrels of produced water from within the earth berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Bradley Blevins</i>	Approved by Environmental Specialist: <i>Mike [Signature]</i>	
Printed Name: Bradley Blevins	Approval Date: 9/23/15	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	Attached <input type="checkbox"/>	
Date: 9-22-15 Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/25/15**

2RP-3293