

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526627950 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company	RKI E&P, LLC	Contact	Zack Laird
Address	210 Park Ave. - Ste. 700, OKC, OK 73102	Telephone No.	405-987-2213
Facility Name:	North Brushy Draw Fed 35-6H	Facility Type :	Oil and Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42293
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	25S	29E	175	FNL	2290	FEL	Eddy

Latitude: 32.0929574 Longitude: -103.95337

NATURE OF RELEASE

Type of Release: Drilling Mud/Frac Fluid	Volume of Release: 760 Bbls	Volume Recovered: 600 Bbls
Source of Release 5.5" x 9.675" annulus	Date and Hour of Occurrence 09/17/15 - 0200hrs MT	Date and Hour of Discovery 09/17/15 - 0200hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson/Shelly Tucker (R/M)	
By Whom? Zack Laird	Date and Hour: 09/17/15 - 1000hrs and 1715hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A



Describe Cause of Problem and Remedial Action Taken.*

During stage 8 stimulation operations an unknown downhole failure (i.e. casing part) caused communication between 5.5" and 9.625" casing, pressure relief valve plumbed to "B" section of wellhead parted under pressure and allowed well flow on surface for approximately 1.5hrs.

Describe Area Affected and Cleanup Action Taken.*

Fluid accumulated on well pad and ran off location to the South for approximately .5 miles

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Zack Laird		Approved by Environmental Specialist: 	
Title: Sr. EHS Manager		Approval Date: 9/23/15	Expiration Date: N/A
E-mail Address: Zlaird@rkixp.com		Conditions of Approval:	
Date: 09/17/15 Phone: 405-987-2213		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/25/15

2RP-3278