

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

ML Quadv Angle, LLC

3a. Address

7008 Salam Ave. Lubbock TX

3b. Phone No. (include area code)

806 797-8621

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2304 FBL. 2310 FEL Sec. 35 Twp. 17s. Rng. 27E

5. Lease Serial No.

LC 057798

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

South Red Lake Grouburs #18

9. API Well No.

30-015-00627

10. Field and Pool, or Exploratory Area

S. Red Lake GN.GB.SA

11. County or Parish, State

Eddy NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

FINAL PLUG AND ABANDON

1. Place 50 CF Plug @ 1530'.

2. Tag Plug @ Approx. 1000'. and 7" CASING at 600'.

3. Perforate 4.5" CASING @ 980' or 20' Above Tag of 50 CF Plug if Above 1000'.

4. Circulate 50 SAX through Perforations @ 980' Pumping down 4.5" CASING

5. Cut off CASING 6' below Ground level. Install Marker 75' West (Not inside offset Placem.)
Noting Offset Placem. AS Per Eddy County Road Dept. Request.

6. Reclaim Area immediately Around well head to not degrade integrity of Road bed or
Effect two adjacent PIRLINE AND UTILITY RIGHT of WAYS.

7. Work shall begin Monday MAY 19 2003. @ 800am MST.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

H.E. Buddy Delong

Title

Agent

Signature

H.E. Buddy Delong

Date

5-15-03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

(ORIG. SGN) ALEXIS C. SWOBODA

PETROLEUM ENGINEER

Date

MAY 15 2003

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office