Submit 3 Copies 10 Appropriate District	State of New M	lexico	Form C-103
Office District I	Energy, Minerals and Nat	tural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO:
District II	OIL CONSERVATIO	N. DIVICION	30-015-34185
1301 W. Grand Ave., Artesia, NM 88210	-		5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE X FEE	
District IV	Santa Fe, NM 8	37505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			OG-5851-1
87505			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Southwest Empire 8 State Com	
PROPOSALS.)	ATION FOR PERMIT" (FORM C-101)	FOR SUCH	8. Well Number
/	Gas Well X Other		1
	Jas Well A Other	RECEIVED	9. OGRID Number
2. Name of Operator		HEUEIVEL	1
Mewbourne Oil Company		DEC 1 2 2005	14744
3. Address of Operator			10. Pool name or Wildcat
PO Box 5270 Hobbs, NM 88240	C	nu-matesia	Millman Strawn / Illinois Camp Morrow
4. Well Location			
Unit Letter H	1650 feet from the N	line and	810 feet from theE_line
Section 8	Township 18S	Range 28E	
	11. Elevation (Show whether D	R, RKB, RT, GR, etc.,	
	3638' GL		
Pit or Below-grade Tank Application or	Closure [_]		
Pit typeDepth to Groundwa	terDistance from nearest fresh	water well Dist	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	onstruction Material
12. Check A	ppropriate Box to Indicate	Nature of Notice,	Report or Other Data
NOTICE OF IN	TENTION TO	l cun	OF OUT DEDOOD OF
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPORT OF:
NOTICE OF IN PERFORM REMEDIAL WORK □	TENTION TO: PLUG AND ABANDON □	SUB REMEDIAL WOR	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ALTERING CASING
	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING -	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR COMMENCE DRI CASING/CEMEN	K
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR COMMENCE DRI CASING/CEMEN	K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC	K
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and	K
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state alork). SEE RULE 1103. For Multiple Company Co	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed work or recompletion. Mewbourne Oil Company was productive to the proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. A	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394',
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed or completion of starting any proposed work or recompletion. Mewbourne Oil Company was producted to 10214' to 10234', 10068' to 10076' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' and 10	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. A	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed work or recompletion. Mewbourne Oil Company was productive to the proposed work or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. A	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394',
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed or completion of starting any proposed work or recompletion. Mewbourne Oil Company was producted to 10214' to 10234', 10068' to 10076' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' and 10	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. A	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394',
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed or completion of starting any proposed work or recompletion. Mewbourne Oil Company was producted to 10214' to 10234', 10068' to 10076' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' and 10	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. A	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394',
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed or completion of starting any proposed work or recompletion. Mewbourne Oil Company was producted to 10214' to 10234', 10068' to 10076' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' and 10	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. A	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394',
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed or completion of starting any proposed work or recompletion. Mewbourne Oil Company was producted to 10214' to 10234', 10068' to 10076' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' to 10234' and 10214' and 10	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. A	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At	ALTERING CASING LLING OPNS. PAND A T JOB #3588 d give pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394',
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed or completion of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state alok). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. Ad 9986' to 9991') and Strawn per	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete the complete	ALTERING CASING LLING OPNS. P AND A T JOB T JOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOTHER: The starting any proposed or completion of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state alock). SEE RULE 1103. For Multiple Strawn at 9554' to 9562'. Ad 9986' to 9991') and Strawn per above is true and complete to the	REMEDIAL WOR COMMENCE DRI CASING/CEMEN' OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to 9562'). Complete to 9562'	ALTERING CASING LILING OPNS. PAND A TJOB TJOB TJOB State of the partial part of proposed completion and the part of proposed completion and the part of proposed completion of the part of the
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or comples of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a grade tank has been/will be constructed or complete the constructed or complete.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state alok). SEE RULE 1103. For Multiple Strawn at 9554' to 9562'. Add 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines.	REMEDIAL WOR COMMENCE DRI CASING/CEMEN' OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to 9562'). Complete to 9562'	ALTERING CASING LLING OPNS. P AND A T JOB T JOB
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or comples of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a grade tank has been/will be constructed or complete the constructed or complete.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ceted operations. (Clearly state alok). SEE RULE 1103. For Multiple Strawn at 9554' to 9562'. Add 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines.	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to the second s	ALTERING CASING LLING OPNS. P AND A T JOB #3588 degive pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394', Cleaned out to PBTD at 10548'. Put back on e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Compositions of the second strawn at 9554' to 9562'. A d 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines.	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to the properties of my knowledge a general permit Hobbs Regulatory	ALTERING CASING LLING OPNS. P AND A T JOB T JOB T JOB T JOB T JOB P AND A T JOB T
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Compositions of the second strawn at 9554' to 9562'. A d 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines.	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to the properties of my knowledge a general permit Hobbs Regulatory	ALTERING CASING LLING OPNS. P AND A T JOB T JOB T JOB T JOB T JOB P AND A T JOB T
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Compositions of the second strawn at 9554' to 9562'. A d 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines.	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to the properties of my knowledge a general permit Hobbs Regulatory	ALTERING CASING LLING OPNS. PAND A T JOB #3588 digive pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394', Cleaned out to PBTD at 10548'. Put back on e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Compositions of the second strawn at 9554' to 9562'. A d 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines.	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to the properties of my knowledge a general permit Hobbs Regulatory	ALTERING CASING LLING OPNS. PAND A T JOB #3588 digive pertinent dates, including estimated date tach wellbore diagram of proposed completion OHC #3588 for Morrow (10350' to 10394', Cleaned out to PBTD at 10548'. Put back on e and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan .
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mewbourne Oil Company was product 10214' to 10234', 10068' to 10076' and production 12/08/05. I hereby certify that the information a grade tank has been/will be/constructed or of SIGNATURE Type or print name Kristi Green For State Use Only	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL MULTIPLE COMPL Ceted operations. (Clearly state alock). SEE RULE 1103. For Multiple Cing Strawn at 9554' to 9562'. Add 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines. TITLE E-mail a	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to the properties of my knowledge of the properties of t	ALTERING CASING LLING OPNS. P AND A T JOB P AND A T JOB T JOB P AND A T JOB T
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. Mewbourne Oil Company was production 12/08/05. I hereby certify that the information a grade tank has been/will be constructed or of SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL eted operations. (Clearly state al rk). SEE RULE 1103. For Multiple Compositions of the second strawn at 9554' to 9562'. A d 9986' to 9991') and Strawn per shove is true and complete to the closed according to NMOCD guidelines.	REMEDIAL WOR COMMENCE DRI CASING/CEMENT OTHER: DHC I pertinent details, and ple Completions: At pplied and received I fs (9554' to 9562'). Complete to the properties of my knowledge a general permit Hobbs Regulatory	ALTERING CASING LLING OPNS. P AND A T JOB P AND A T JOB T JOB P AND A T JOB T