Form 3160-5 (November 1994)

## **OCD-ARTESIA**

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**


FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996 5. Lease Serial No.


## **SUNDRY NOTICES AND REPORTS ON WELLS**


NMNM28172

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.  SUBMIT IN TRIPLICATE - Other Instructions on reverse side					If Indian, Allottee or Tribe Name  7. If Unit or CA/Agreement, Name and/or No.	
Oil Well  Gas Well					8. Well Name and No.	
2. Name of Operator Gruy Petroleum Management Co.			Adrianne 6 Federal No. 1  9. API Well No.			
			9. API Well No. 30-015-34319			
			72-401-3111		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Undesignate	ed Chosa Draw; Morrow
SHL: 200' FNL & 1700' FWL Sec. 6-T25S-R6E				11. County or Parish, State		arish, State
BHL: 750' FNL & 1550			Eddy Co., N	ſΜ		
12. CHECK A	APPROPRIATE BOX(ES) TO	O INDICATI	E NATURE (	OF NOTICE, R	EPORT, OR O	THER DATA
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	☐ Acidize	Deepen		Production (Start	/Resume)	Water Shut-Off
Nonce of Milent	Alter Casing	☐ Fracture T	reat 🔲	Reclamation		Well Integrity
Subsequent Report	Casing Repair	New Cons	struction 🗆 🗖	Recomplete	⊠:	Other Alter pit and solid
Final Abandonment Notice	Change Plans	Plug and			andon	cuttings disposal
	Convert to Injection	Plug Back		Water Disposal		
Drill fluids will be contain will be seperated by a see The drying area will be list thick retention liner will anchored down. A pumpand reused. After drying clay barrier. Drill cutting will be folded over the cutseepage and the cell will	cuttings pit construction by ained in steel pits in a close eries of solids removal equilined with a 2' clay barrier all cover the drying area and up off system will pump any ag, cuttings will be disposed the many off system that the disposed of the cuttings and capped with a 2' be filled with 3' to 4' of topolat, cuttings burial cell diagrams.	d circulatin pment. Dri and surrour will extend acumulate d of in a 50' cuttings dr 20 mil mem o soil and le	g system. Full cuttings would by a 2' a minimum defluids in the X 50' cutting area and brane cap.	luids will be clill be hauled to x 2' ring levee of 2' over the ne ring levee to gs burial cell. d encapsulate An additional ontoured to contile.	leaned and reto a 100' x 70' and a 2' earthearthen berm to the rig holding. The bottom with a 12 mil 2' clay barrier aform to the o	used and drill cuttings cuttings drying area. nen berm. A 12 mil where the liner will being tanks to be cleaned will be lined with a 2' liner. The 12 mil liner will be added to preven
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Zeno Farris			Title  Manager Operations, Administration			
Signature 2 Ing Faring			Date 12-15-05			
	THIS SPACE FO	OR FEDERA	. <del></del> -			
Approved by /S/	/ Joe G. Lara		Pëtfol	eum Engi	neer Date	DEC 2 1 2005
Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant to o	e attached. Approval of this notice	does not warra in the subject	nt or Office	CARLS	BAD FIE	LD OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.







Zero Discharge Overview