

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

OCT 29 1990

WELL API NO.	3001522330
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Polk A
8. Well No.	1
9. Pool name or Wildcat	South Loving Delaware

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator OXY USA Inc. ✓
3. Address of Operator P.O. Box 50250 Midland, TX. 79710	4. Well Location Unit Letter B : 660 Feet From The North Line and 2310 Feet From The East Line Section 17 Township 23S Range 28E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3027'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD-12574' PBTD-6378' Delaware perms-5880'-5894' It is proposed to Plug & Abandon in the following manner:

1. POOH w/ tbg & pkr
2. RUWL, Set 7" CIBP on WL @ $\pm 5600'$. Press test csg to 1000#.
3. RIH w/ tbg to 5600'. Circ hole w/ 9.5 ppg mud laden fluid. Spot 200' cement plug on top of CIBP & across 9-5/8" csg shoe from 5600-5400'.
4. POOH w/ tbg. ND BOP & WH. Weld lift sub on 7" csg. PU on 7" csg. Run free point. Cut off 7" csg @ $\pm 3450'$ (TOC-3550'-CBL). POOH LD csg.

(See other side)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 10/26/90
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 9156855717

(This space for State Use)

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE 11-7-90
CONDITIONS OF APPROVAL, IF ANY:

5. RIH w/ tbg to 3550'. Circ hole w/ 9.5 ppg mud laden fluid. Spot 200' cement plug half in and half out of 7" csg stub @ 3450'. POOH w/ tbg to 2500'. WOC, RIH tag plug @ 3400'. POOH to 2500'.
6. Spot 100' cement plug across top pf Delaware @ 2500-2400'. POOH to 2000'. Spot 100' cement plug across top of salt 2000-1900'. POOH to 450'.
7. Spot 100' cement plug half in and half out of 13-3/8" csg shoe @ 400' from 450-350'. POOH w/ tbg.
8. Cut off WH & csg below GL. RIH w/ tbg to 50'. Spot cement plug from 50'-surface. Install dry hole marker. Rel PU.
9. Clean up location

Mike Williams-NMOCD-verbally approved P&A procedure

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

NOV 14 '90

O. C. D.

WELL API NO.	3001522330
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Polk A
8. Well No.	1
9. Pool name or Wildcat	South Loving Delaware

SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA, OFFICE
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
OXY USA Inc. ✓

3. Address of Operator
P.O. Box 50250 Midland, TX. 79710

4. Well Location
Unit Letter B : 660 Feet From The North Line and 2310 Feet From The East Line
Section 17 Township 23S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3027'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD-12574' PBTD-6378' Delaware perms 5880'-5894' The well was plugged and abandoned in the following manner.

POOH w/ 2-7/8" tbg and pkr. RIH w/ 7" CIBP and set @ 5600'. Test csg to 1000#, held OK. Circ hole w/ 9.5ppg mud laden fluid. Spot 35sx Cl C cmt (200') on top of CIBP, New PBTD-5400'. RIH w/ jet cutter, cut csg @ 3350', POOH w/ 82 jts 7" csg (TLS-3329.5'). RIH w/ 2-7/8" tbg, circ hole w/ 9.5ppg mud. Spot 35 sx Cl C cmt (200') plug from 3469'-3269', half in and half out of 7" csg @ 3350'. POOH, WOC-4hrs. RIH tag plug @ 3342'. Spot 26sx Cl C cmt (70') plug from 3342'-3288', POOH to 2486', WOC, SION. Spot 50sx Cl C cmt (100') plug from 2486'-2386' across top of Delaware. POOH to 2282', spot 50sx Cl C cmt (100') plug from 2282'-2182' across top of salt. POOH to 450', spot 50sx Cl C cmt (100') plug from 450'-350'. POOH to 50', spot surface plug. POOH, cut off wellhead, install dry hole marker, RDPU. Well P&A'd 10/26/90.

Mike Stubblefield w/ NMOC D witnessed job.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE F.A. Vitrano TITLE Region Operations Manager DATE 11/12/90

TYPE OR PRINT NAME F.A. Vitrano (Prepared by David Stewart) TELEPHONE NO. 9156855717

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE NOV 16 1990

CONDITIONS OF APPROVAL, IF ANY: