

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Covernor

10 Release 1/26/06 Acting Director Oil Conservation Division RECEIVED JAN 25 2006 **UUU-MITERIA** Form C-103 Report of Plugging for your Burton Flat Deep Unit #27 G-2-T21S-R27E API 30-015-24789 cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final 1. All pits have been closed as per Rule 50. A. B. 2. Rat hole and cellar have been filled and leveled. 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.) 4. The location has been leveled as nearly as possible to original top ground contour and has been 5. The dead men and tie downs have been cut and removed. 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been 7. All environmental concerns have been addressed as per OCD guidelines. The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

> Van Barton Field Rep. II

Joanna Prukop

Cabinet Secretary

18 January 2006

inspection.

approval.

Devon Energy Production Company P. O. Box 250 Artesia, NM 88211-0250

cleared of all junk and equipment.

leveled and cleared of all junk & equipment.

Oil Conservation Division * 1220 South St. Francis Drive * Santa Fe, New Mexico 87505 Phone: (505) 476-3440 * Fax (505) 476-3462 * http://www.emnrd.state.nm.us

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and

Submit 3 Copies To Appropriate District	State of New Mexico			Form C	
Office. District I	Energy, Minerals and Natural Resources			Revised June 10), 2003
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
District II	OU CONSERVATION	OIL CONSERVATION DIVISION			
1301 W. Grand Ave., Artesia, NM 88210				of Lease	
District III 1220 South St. Francis Dr.		STATE	FEE		
District IV Santa Fe, NM 87505		6. State Oil & Ga	s Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM			0428854		
87505	CEC AND REPORTS ON WELL	7	7 Laga Nama as	Linit Agramant N	ama
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name Burton Flat Deep Unit		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Buiton riat Deep	Omi	
PROPOSALS.)		8. Well Number			
1. Type of Well: Oil Well Gas Well Other RECEIVEL		ECEIVE	27		
Oil Well 🛛 Gas Well 🔲	Other	ECEIVEL.			
2. Name of Operator		IAN 0 5 2006	9. OGRID Numb	er	
Devon Louisiana Corporation	von Louisiana Corporation		169355		
3. Address of Operator	COUPAR		10. Pool name or		
20 North Broadway, Suite 1500, Ol	clahoma City, Oklahoma 73102		Undesignated Fen	ton/Delaware NE	
4. Well Location					
Unit LetterG:_16	12'feet from the _North	line and	1980'feet fron	n theEast	line
Section 2		nge 27E	Eddy	County	
	11. Elevation (Show whether DR	R, RKB, RT, GR, etc.) []	4.04	
	3195' GR			120	
12. Check A	Appropriate Box to Indicate N	Vature of Notice,	Report or Other	Data	
			SEQUENT RE		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOF			ALTERING CASIN	GП	
, 21 (1 O) (III (1 E) II E V O) (II C	. 2007				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.□	PLUG AND	\boxtimes
_	_		_	ABANDONMENT	_
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	ND 🗌		
	COMPLETION	CEMENT JOB			
OTHER:	П	OTHER:			
					Ц_
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion					
or recompletion.					
1. MIRU on 9-10-05. Pulled existing					
2. Set CIBP in 5-1/2" casing at 2710'. This isolates Delaware perfs from 2744-3050'. Circulated hole with 9 ppg mud. Spot 30 sx					
cement on top of CIBP at 2710'.					
3. Tagged TOC at 2423'. (8-5/8" casing shoe at 2573').					
4. Cut 5-1/2" casing at 600'. POOH with casing. Spot 50 sx cement at 680'. Tagged TOC at 456'. (13-3/8" casing shoe at 600').					
5. Circulated cement from 62' to surface. Well plugged and abandoned on 9-14-05.					
$\overline{}$		· · · · · · · · · · · · · · · · · · ·			
I hereby certify that the information	above is true and complete to the l	est of my knowledg	ge and belief.		
K. to KO) An				
SIGNATURE / JUSTIN / LIA	TITLE: Eng	ineering Technician	DAT	E9-14-05	
1 45	Michael	~.			
Type or print name Ronnie G. Slac	k E-mail address: Ronni	e.Slack@dvn.com	Telephone	No. 405-552-4615	
(This space for State use)					
	_			1A & 1 69 /2	ን ስበድ
APPPROVED BY	TITLE_			DATEJAN 26	2000
Conditions of approval, if any:	ø.				
	•				
-					

