Received Some 4 2010

Expiration Date:

Attached [

7RP- 441

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Title: Project Manager

E-mail Address: ike.tavarez@tetratech.com

Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Revised October 10, 2003 Submit 2 Copies to appropriate

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

·····				<u>ა</u>	anta i	e, NW 873	DUD						
Release Notification and Corrective Action													
					OPERA'	☐ Initi	al Report	\boxtimes	Final Repo				
Name of Co	ompany C	Contact Pat Ellis											
Address 55		Telephone No. (432) 685-4332											
Facility Na	me Polais	Facility Type Tank Battery											
Surface Ow	nor Ender	Lease No. 30-015-31565											
Surface Ow	nei reucia	<u></u>		Mineral (Lease 140. 30-013-31303								
	·	, _				N OF REI	LEASE			······			
Unit Letter	Section	Township	Range	Feet from the	North	√South Line	Feet from the	East/\	West Line	County			
F	17	17S	30E	2310	North	1	2210	West		Eddy			
		110		<u> </u>	·		·						
Latitude N 32°50.105 Longitude W 103°59.751													
NATURE OF RELEASE													
Type of Release Produced water										olume Recovered 15 bbls			
Source of Release							•			and Hour of Discovery			
Heater Was Immediate Notice Given?							Unknown 2/15/10 2/15/10 If YES, To Whom?						
44 48 Innican	ne Nobee C		Yes [No Not Re									
By Whom? Rick Wright							Date and Hour 2/15/10 If YES, Volume Impacting the Watercourse.						
Was a Watercourse Reached? ☐ Yes ☑ No							N/A						
If a Watercou	rse was Imp	acted, Descri	be Fully.*	,		<u> </u>				T			
N/A													
Describe Cause of Problem and Remedial Action Taken.*													
The composition	n from the	flow line to th	a baatar ti	eater was defecti	ua The	failed bester/	fla lina aannaat		nonaised				
The connection	ni itolli ule i	inon iilie to ui	ie neater ti	eater was defecti	vc. 1116	raneo neater/	now time connect	JOH Was	теранеа.				
Describe Area													
The spill occu	rred outside	the facility fi	irewalls.	Majority of the sp	ill was	overspray wes	t of the tank batte	ry. The	area was a	issessed to e	valuate	the spill.	
All samples w	ere below ti twith clean	he KKAL for soil A closu	TPH and . re-renort b	BTEX. Elevated as been prepared	chloride and sul	e concentration omitted to the	is were removed NMOCD for revi	and hau ew and	led to CRI	tor disposal.	The	excavation	
was trackinice	WIGH CHORN	3011. 71 01030	io report i	ias occii proparca	and so	mutted to the	THINGED TO TEVE	CW IIII	арргочат.				
ĺ													
I baraby certif	v that the in	formation give	en above	is true and comple	ete In th	a best of my k	noulades and un	daretan	d that auren	iont to NIMO	CD rul	ac and	
				l/or file certain re									
public health of	or the enviro	nment. The a	acceptance	of a C-141 repor	t by the	NMOCD mar	ked as "Final Re	port" do	es not relie	ve the opera	tor of 1	iability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
/	11.						OIL CONS	ERV	ATION I	OIVISION	V		
//	//// 14				1		<u></u>						
Signature /	4 V	- X -				Approved by District Supervisor:							
Printed Name:	Ike Tavare:	, 0		/	Approved by District Supervisor: Mulh								

Approval Date:

Phone: (432) 682-4559

Conditions of Approval: