

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

NOV 03 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1530834217

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: BEU #169	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35169
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 17	Township 21S	Range 28E	Feet from the 660	North/South Line North	Feet from the 1830	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.485733° Longitude -104.111387°

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 6 bbls	Volume Recovered 1 bbl
Source of Release Tank Overflow	Date and Hour of Occurrence 10/26/2015 time unknown	Date and Hour of Discovery 10/26/2015 1 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

Vessel liquid level controller failed to shut off causing gas to dump into tanks. Fluid was released from tank hatches. Controller was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The leak affected 774 square feet of caliche within the tank battery earthen berm. Vacuum trucks recovered standing fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Approved by Environmental Specialist: 	
Title: Assistant Remediation Foreman	Approval Date: 11/4/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 11/03/2015 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 12/4/15	

\* Attach Additional Sheets If Necessary

2RP-3375