Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR Artesia BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY N	OTICES AND REPORTS ON WELLS	
Do not use this	form for proposals to drill or to re-enter an	
	Hon form 2160 2 (ADD) for such proposals	

5. Lease Serial No. NMNM01165

	NO HOES AND KEPOKI			1	1 41411 4141	01100		
Do not use thi abandoned wel	is form for proposals to dr II. Use form 3160-3 (APD)	ill or to re- for such p	enter an roposals.	,	6. If Indian	Allottee or Ti	ribe Name	
SUBMIT IN TRI	PLICATE - Other instruction	ons on rev	erse side.		7. If Unit o	r CA/Agreeme	ent, Name and/or No.	
Type of Well	ner	ı			8. Well Nan DERRIN		DA FEDERAL 2H	
Name of Operator MEWBOURNE OIL COMPAN	Contact: JA Y E-Mail: jlathan@mewl		HAN		9. API Wel 30-015	No. -42969-00->	X1	
3a. Address P O BOX 5270 HOBBS, NM 88241		b. Phone No. Ph: 575-39	(include area code 3-5905	;)	10. Field ar RUSSE	d Pool, or Exp LL	oloratory	
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)				11. County	or Parish, and	State	
Sec 18 T20S R29E Lot 1 665F 32.344420 N Lat, 104.071780					EDDY (COUNTY, N	IM	
12. CHECK APPR	ROPRIATE BOX(ES) TO II	NDICATE	NATURE OF	NOTICE, RE	PORT, OF	OTHER D	DATA	
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION				
☐ Notice of Intent	☐ Acidize	☐ Deep	en	☐ Producti	on (Start/Re	sume) [☐ Water Shut-Off	
*	☐ Alter Casing	☐ Fract	ture Treat	☐ Reclama	tion	C	☐ Well Integrity	
Subsequent Report	☐ Casing Repair		Construction	☐ Recomp		ī	☑ Other Drilling Operations	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	□ Tempora	•	n '	Drining Operations	
13. Describe Proposed or Completed Ope	☐ Convert to Injection	☐ Plug		☐ Water D			,'	
testing has been completed. Final Abdetermined that the site is ready for final Abdetermined that the site is ready for final Class C (35:65:6) w/additives. Mixed @ 14.8#/g w/1.32 yd. Popen DV tool w/6803. Did not spool & test pack-off to 2000#.	nal inspection.) 026'. Ran 3026' of 9 5/8" 36/8 Mixed @ 12.5 #/g w/2.11 yo lug down @ 3:30 AM 07/17/ circ emt off of DV tool. ND B . NU BOPE. Tested BOPE	# J55 LT&0 d. Tail w/20 15. Set ext 3OP & set v to 3000# &	C csg. Cemente 0 sks Class C ernal csg pkr w vellhead slips w Annular to 150	ed with 400 sk w/additives. //2200#. Drop v/90k#. NU cs 00#. Cmt 2nd	s Lite bom kiy g stage	• ,	SERVATION	
w/200 sks Class C w/additives 14.8#/g w/1.33 yd. Plug down pit. WOC. At 6:30 P.M. 07/18/ 3/4" bit.	. Mixed @ 13.5#/g W/1.74 y @ 7:30 A.M. 07/17/15. Clos 15, tested csg to 1500# for 3	ed DV tool 30 minutes,	w/2000#. Circ held OK. Drille	0#. Circ 88 sks of cement to VK. Drilled out with 8			CT 3 0 2015	
Chart & schematic attached.	Accepted for the Neutropia	, , , ,				RECEI	VED	
	(2) 11	/3/ıs′						
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #310 For MEWBOURNE sitted to AFMSS for processin	EOIL COMP	'AÑY, sent to th	ne Carlsbad	-	2SE)		
Name (Printed/Typed) JACKIE LA	ATHAN		Title AUTHO	DRIZED REPI	RESENTA	TIVE		
Signature (Electronic S	Submission)	'	Date 07/24/2	2015		 		
	THIS SPACE FOR	FEDERA	L OR STATE	OFFICE US	E		•	
Approved By ACCEPT	ED]	DAVID R _{Title} PETROLE		ER		Date 10/22/2015	
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	itable title to those rights in the sub		Office Carlsba	nd				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s					e to any dep	artment or age	ncy of the United	

Additional data for EC transaction #310175 that would not fit on the form

32. Additional remarks, continued

Bond on file: NM1693 nationwide & NMB000919

MAN WELDING SERVICES INC

Company New BONTNE	Date 7-/7-/5
Lease Dentinger 18 B3DA Fed. 3H	County Edy N.M.
	Plug & Drill Pipe Size // 622 4/2XH
	fold Pressure: 1400 Annular Pressure: 1200
Accumulator Fi	unction Test - OO&GO#2
To Check - USABLE FLUID IN THE NITRO	
	Arc C. II. HOD is also d

- Make sure all rams and annular are open and if applicable HCR is closed.
- Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
 - 1. Open HCR Valve. (If applicable)
 - 2. Close annular.
 - 3. Close all pipe rams.
 - 4. Open one set of the pipe rams to simulate closing the blind ram.
 - 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
 - 6. Record remaining pressure 2/00 psi. Test Fails if pressure is lower than required.
 - a. (950 psi for a 1500 psi system) b. {1200 psi for a 2000 & 3000 psi system}
 - 7. If annular is closed, open it at this time and close HCR.

To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)

- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 - a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop 1000 psi. Test fails if pressure drops below minimum.
- Minimum: a. [700 psi for a 1500 psi system] b. [900 psi for a 2000 & 3000 psi system]

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time 137 . Test fails if it takes over 2 minutes.
 - a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)



WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Lovington, NM • 575-396-4540

Pg. 1 of 2

company: Mew BOUTDe	Date: 7-17-15	Involce # B 50647
Lesse: Der Minger 18 B3DA Fer		terson Riem 75
Plug Size & Type: 1/622	Drill Pipe Size 4/2XH	Tester: Doniel Waleland
Required BOP: 3000	Installed BOP: 5000	
'Appropriate Casing Valve taust Br. Open Quiling BOP Test '	Nanajo	Check Valve Must Be Open/Disabled To Test Kill Line Valves
Annular #15 Pipe Rams #12 Blind Rams #13 #11 #10 #9 Pipe Rams #14 Pipe Rams #14	#26 #2 #5 #6 #3 #5 #6 #1 #88 Manu #1 Mud Gauge Walve #16	#18 W

]
·
y βrdig≓ w
erene bi bili
:
3
,







