Cafe C-14/ Submission

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztso, NM 87410
District IV
1220 S. St. Francis Dr., Sprin Fe. NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Bil S. First St., Artesia, NM 88210	energy windcists and Mar	Revised August 8, 2011			
District III 1000 Rio Brazos Roed, Aztro, NM 67410	Oil Conservation Division		Submit I Co	py to appropriate Di accordance with 19.	strict Office in .15.29 NMAC.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		South St. Francis Dr. nta Fe, NM 87505			
	والمراجع والمستوال والمستوالين والم والمستوالين والمستوالين والمستوالين والمستوالين والمستوالين والمستوالين والمست		-41		
Release Notification and Corrective Action					
NAB 1531631260	OPER		X Ini	tial Report 🔲	Final Report
Name of Company Oxy Permian Ltd. Address 6 Desta Drive, Midland, TX 79705	Contact Telephon	Dusty Wilson e No. 432-685	5771		
Facility Name Codar Canyon 15 SWD #001		ype Battery	<u> </u>	<del></del>	
Surface Owner Brantley-McDonald	Mineral Owner		APIN	io. 30-015-42797	
LOCATION OF RELEASE					
K 15 24S 29E	from the North/South Line		East/West Line	County Eddy	
Latitude 32.21710 Longitude 103.97642					
NATURE OF RELEASE					
Type of Release Produced water		of Release 200 bb	la Volume	Recovered 0 bbls	
Source of Release Pailure of a transfer line clamp	Date and	Hour of Occurrence		Hour of Discovery	
Was Immediate Notice Given?	( 10/11/15 If YES,	Fo Whom?			
☐ Yes ☑ No ☐ Not Required		Heather Patterson, Mike Bratcher			
By Whom? Kathy Purvis @ BBC International Was a Watercourse Reached?		Hour 10/13/15			
Was a Watercourse Reaction! ☐ Yes ☑ No	11 725,	olume impacting the	le Watercourse.	NM OIL CO	ONSERVATIO
If a Watercourse was Impacted, Describe Fully.*					i
				NOV	1 1 2015
		•	ė	D.C.	
Describe Cause of Problem and Remedial Action Taken		•			EIVED
A transfer line clamp caused 200 bbls of produced water	r to leak on to the ground. No	fluids were recover	ed and the clamp	was replaced.	
Describe Area Affected and Cleanup Action Taken.*	<del></del> ,				<del></del>
Samuel Committee and the second s					{
The affected area is approximately 100' x 250' on and off location. Remediation will be completed in accordance with the remediation plan approved by NMOCD.					
And the second s					
I hereby certify that the information given above is true	and complete to the hard of ma	le and adam and ma	James and Alice and	ment to NMOCD and	les and
regulations all operators are required to report and/or fill	e cortain release notifications a	nd perform correctly	ve actions for rele	eases which may end	Sanger
public health or the cuvironment. The acceptance of a C should their operations have failed to adequately investi	-141 report by the NMOCD n	arked as "Final Rep	on" does not reli	love the operator of i	iability
or the environment. In addition, NMOCD acceptance of	la C-141 report dues not rellev	e the operator of res	realibility for e	nmpliance with any o	other .
federal, state, or local laws and or regulations.	<del></del>				
	}	OIL CONSI	ERVATION	DIVISION	i
Signature:					f .
Printed Name: Dust Wilson	Approved by	Environmental Sper	cialist: 12	1/	
Title: Environmental Advisor	Approval Dai	Approval Date:			
E-mail Address: : Dusty Wilson@oxy.com	Conditions of	Approval:		Andria Fr	
Date: 11/11/15 Phone:	Remedia	emediation per O.C.D. Rules & Galactinds UBMIT REMEDIATION PROPOSAL NO			
Attach Additional Sheets If Necessary	<del>-</del> ·	17/11	A FIDEOS	Λ ^	0 2296
	LATER	HAN:	41.	– ZK	p. 3384