

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 13 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1532049700

NAME OF COMPANY Devon Energy Production U137		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Contact Garry Michael, Production Foreman	
Facility Name Cotton Draw Unit 153H		Telephone No. 575-513-4895	
		Facility Type Oil	
Surface Owner Federal		Mineral Owner Federal	API No. 30-015-38535

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	3	25S	31E	200	FNL	1980	FEL	Eddy

Latitude: 32.16613000

Longitude: -103.7631000

NATURE OF RELEASE

Type of Release Oil	Volume of Release 3bbl	Volume Recovered 0bbl
Source of Release sight glass on test heater	Date and Hour of Occurrence November 11, 2015 @ 7:45 AM	Date and Hour of Discovery November 11, 2015 @ 7:45 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Kelly Jones, OCD	
By Whom? David Washington, Assistant Production Foreman	Date and Hour Jim Amos, BLM November 11, 2015 11:24 AM Kelly Jones, OCD November 11, 2015 11:17 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

A sight glass on a test heater broke releasing 3bbls oil. Sight glass was immediately isolated to prevent further release and both the sight glass and the drain valve were replaced.

Describe Area Affected and Cleanup Action Taken.*

Approximately 3bbls of oil was released. Size of the affected area was approximately 300' x 150' next to the test heater on the East side of location extending into the pasture. Approximately 2.5bbls were recovered via vacuum truck. An environmental company will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By: <u>[Signature]</u>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sheila.Fisher@dvn.com	Approval Date: 11/16/15	Expiration Date: N/A
Date: 11/12/15 Phone: 575.748.1829	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 12/17/15

2RP-3398