

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

NOV 25 2015

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1533430359

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Dan Suniga: Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-390-5850
Facility Name	Grandi 22 - 2H	Facility Type	Oil Well

Surface Owner	Private	Mineral Owner	Private	API No	30-015-42821
---------------	---------	---------------	---------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	22	22S	27E	1360	North	255	West	Eddy

Latitude: 32.3817083 N

Longitude: 104.1852271 W

NATURE OF RELEASE

Type of Release	Oil Release	Volume of Release	6 BBLS	Volume Recovered	6 BBLS
Source of Release	Victaulic clamp on vapor recovery tower at fill line	Date and Hour of Occurrence	November 20, 2015 4:00 PM	Date and Hour of Discovery	November 20, 2015 4:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD: Mike Bratcher BLM: Jim Amos		
By Whom?	Mike McMahan; Assistant Production Foreman	Date and Hour	OCD: November 20, 2015 @ 5:00 PM BLM: November 20, 2015 @ 5:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.*	N/A				
Describe Cause of Problem and Remedial Action Taken.*	Victaulic clamp on fill line at the vapor recovery tower failed. Production redirected from tower to tanks. Victaulic clamp has been repaired and is back in use.				
Describe Area Affected and Cleanup Action Taken.*	6 BBLS of oil was released from fill line at Victaulic clamp. All 6 BBLS were released into lined containment. Vacuum truck recovered all of the released oil. No holes were found in the liner. No further action required.				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: Sandy Farley	OIL CONSERVATION DIVISION				
Printed Name: Sandra Farley	Signed By: <u>Mike Bratcher</u>				
Title: Field Admin Support	Approved by Environmental Specialist:				
E-mail Address: sandy.farley@dmv.com	Approval Date: 11/30/15 Expiration Date: N/A				
Date: 11/24/2015 Phone: 575.746.5587	Conditions of Approval: FINAL Attached <input type="checkbox"/>				

* Attach Additional Sheets If Necessary

2RP-3415