Submit 1 Copy To Appropriate District	State of New	Mexico		Form C-10	
Office District I – (575) 393-6161	Energy, Minerals and N		Rev	vised August 1. 20	
1625 N. French Dr., Hobbs, NM 88240	Line By, minerally and the		WELL API NO.	Ľ	
<u>District II</u> - (575) 748-1283	OIL CONFEDMATE	ON DIVISION	30-015-23815		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	a	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. F			FEE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM	1 87505	6. State Oil & Gas Lease		
1220 S. St. Francis Dr., Santa Fe, NM		i -	NM 703-69	110.	
87505 CLNDDX NOT	LOCA AND DEPODTS ON WE				
(DO NOT USE THIS FORM FOR PROP	TICES AND REPORTS ON WE		7. Lease Name or Unit A	greement Name	
DIFFERENT RESERVOIR. USE "APPL"				-	
PROPOSALS.)		,	DONNELLY KELLY ST 8. Well Number 3		
1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other			8. Well Number 3		
2. Name of Operator			9. OGRID Number		
Alamo Permian Resources. LLC			274841		
3. Address of Operator			10. Pool name or Wildca		
415 W. Wall Street, Suite 500, N	1idland, TX 79701 ·		RED LAKE; QN-GB-SA	N ANDRES	
4. Well Location ·	•				
Unit Letter O : 990	feet from the S line and	2270 feet from	the E line		
Section 8 Town		2270 Recention 28E NMPM		DDY	
Section 8 10Wh					
	11. Elevation (Show whether	DK, KNB, KI, GK. etc			
	······································				
	Appropriate Box to Indicate				
	CHANGE PLANS	COMMENCE DI	RK ALTER		
PULL OR ALTER CASING	Image plans MULTIPLE COMPL	COMMENCE DE CASING/CEMEI	RILLING OPNS.		
	•		RILLING OPNS.	-	
PULL OR ALTER CASING		CASING/CEMEI	RILLING OPNS. PAND		
PULL OR ALTER CASING DOWNHOLE COMMINGLE		CASING/CEMEI OTHER: RI		A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. PAND	A [
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. P AND NT JOB.	A [ing estimated d liagram of	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. P AND NT JOB.	A [ing estimated d liagram of	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES	ing estimated d liagram of CONSERVATI SIA DISTRICT	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES	A [ing estimated d liagram of	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES	A [ing estimated d diagram of CONSERVAT SIA DISTRICT	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES NOV	A [ing estimated d diagram of CONSERVAT SIA DISTRICT A 1 6 2015	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	OTHER: RI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES NOV	A [ing estimated d diagram of CONSERVAT SIA DISTRICT	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES NOV	A [ing estimated d liagram of CONSERVAT SIA DISTRICT A 6 2015	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES NOV	A [ing estimated d diagram of CONSERVAT SIA DISTRICT A 1 6 2015	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES NOV	A [ing estimated d diagram of CONSERVAT SIA DISTRICT A 1 6 2015	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	AULTIPLE COMPL	CASING/CEMEI	RILLING OPNS. P AND NT JOB. P ETURN TO PRODUCTION d give pertinent dates, includ mpletions: Attach wellbore c NM OIL C ARTES NOV RE e and belief.	A [ing estimated d liagram of SIA DISTRICT A 1 6 2015 CEIVED	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	AULTIPLE COMPL	CASING/CEMEI	RILLING OPNS. P AND NT JOB. D ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTES NOV	A [ing estimated d liagram of SIA DISTRICT A 1 6 2015 CEIVED	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL I I I <tr< td=""><td>CASING/CEMEI</td><td>RILLING OPNS. P AND NT JOB. ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore of NM OIL C ARTE: NOV RE e and belief. DATE: <u>11/13/</u></td><td>A [ing estimated da liagram of SIA DISTRICT A 1 6 2015 CEIVED</td></tr<>	CASING/CEMEI	RILLING OPNS. P AND NT JOB. ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore of NM OIL C ARTE: NOV RE e and belief. DATE: <u>11/13/</u>	A [ing estimated da liagram of SIA DISTRICT A 1 6 2015 CEIVED	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL I Image: complete to the structure of the struc	CASING/CEMEI	RILLING OPNS. P AND NT JOB. P ETURN TO PRODUCTION d give pertinent dates, includ mpletions: Attach wellbore c NM OIL C ARTES NOV RE e and belief.	A [ing estimated d liagram of SIA DISTRICT A 1 6 2015 CEIVED	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL I I I <tr< td=""><td>CASING/CEMEI</td><td>RILLING OPNS. P AND NT JOB. ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTE: NOV RE e and belief. DATE: <u>11/13/</u> PHONE: <u>432.664.7659</u></td><td>A [ing estimated d diagram of SIA DISTRICT A 1 6 2015 CEIVED</td></tr<>	CASING/CEMEI	RILLING OPNS. P AND NT JOB. ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore c NM OIL C ARTE: NOV RE e and belief. DATE: <u>11/13/</u> PHONE: <u>432.664.7659</u>	A [ing estimated d diagram of SIA DISTRICT A 1 6 2015 CEIVED	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL I I I <tr< td=""><td>CASING/CEMEI</td><td>RILLING OPNS. P AND NT JOB. ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore of NM OIL C ARTE: NOV RE e and belief. DATE: <u>11/13/</u></td><td>A [ing estimated d diagram of SIA DISTRICT A 1 6 2015 CEIVED</td></tr<>	CASING/CEMEI	RILLING OPNS. P AND NT JOB. ETURN TO PRODUCTION d give pertinent dates, includ npletions: Attach wellbore of NM OIL C ARTE: NOV RE e and belief. DATE: <u>11/13/</u>	A [ing estimated d diagram of SIA DISTRICT A 1 6 2015 CEIVED	

· · · ·

DONNELLY KELLY STATE #003					
		Perfs: 2039-2475' OA			
API: 30-015-23815	Lease: NM 703-69	Spud: 06/19/81			
O-8-18S-28E	990FSL & 2270 FEL	P&A:			
Eddy Co., NM	Pool: 3230-ARTESIA;Qu-Grayb-San Andres				

OBJECTIVE: Repair casing leak; acidize.

<u>10/19/15</u>

MI anchor service to pull/test anchors as per requirements. MIRU T rig. Unhang well & unseat pump. POOH laying down rods & pump. ND WH. Wait on flange for BOP. PU BOP. Unset TAC & stood 15 stands in the derrick. LD rest of tubing & BHA. RIH w/4-1/2"x10.5# Weatherford RBP to +/- 900". Set RBP & POOH laying down tubing & retrieving head. ND BOP. Secure WH. RD well servicing rig & moved to edge of location. SDFN.

10/20/15

:

MI Backhoe Services. Dug around well & below surface head. Hole in 4-1/2" csg at Bradenhead slips. Tied onto 4-1/2" csg to kill gas migration to surface. 4-1/2" csg still communicating with 8-5/8" csg. Continue to dig another 5.00". Found another leak in 4-1/2" csg, 12.00" from surface. Cut 8-5/8" csg & 4-1/2" csg. Weld on new top section of 4-1/2" csg (12.00") to surface. Tied onto 4-1/2" csg. Pump $\frac{1}{2}$ bbl water, prod csg still communicating with surface csg. Hook up vac truck & suck water in 8-5/8" csg down 5" below cut-off level. Pump $\frac{1}{2}$ bbl water. Could not see hole. Fenced hole. SDON.

10/21/15

MI Backhoe Services & dig 2' deeper. Strip 8-5/8" csg over 4-1/2" production csg & weld onto 8-5/8" stub. Back-fill hole. Secure well & SDFN.

<u>10/22-27/15</u> Shut down.

<u>10/28/15</u>

MIRU PU. NU WH & BOP. Prep to isolate casing leak.

10/00/15

<u>10/29/15</u> PUL4-1/2"y10.5#y2-3/8" Baker AD-1 renta

PU 4-1/2"x10.5#x2-3/8" Baker AD-1 rental packer. Tag RBP & LD 1 jt tbg. Set pkr. Test tbg, pkr & RBP to 500 PSI. Watch for 15 mins, ok., Release pkr & continue to isolate csg leak. Found bottom of hole @ 28'. Top of csg leak @ 24'. Test csg from 24' to surface, ok. LD pkr. RIH w/tbg OE to 900'. Dump 2 sx sand (12') dwn tbg & flush 2 BW. Wait 1 hr & POOH. Top of sand 12' above RBP. ND BOP & WH. Well ready for cement in the AM. SDFN.

10/30/15

MIRU cement truck. Install swedge & 2" valve. Broke circ w/FW. Mix & pump 34 sx Class "C" cmt w/2% CaCL. Pump csg volume 24' in 4-1/2" csg bringing cmt to surface. Pressure cmt to 250 PSI. Slow bleed-off. Continue to re-pressure until cmt started to set. Close valve, wash pump & lines & hook back to well. Pump $1/10^{th}$ bbls displacement. Well pressure to 350 PSI. Watch pressure f/30 mins, no leaks. Close well-in. RD Southwest. SDFWE f/cmt to set up. Total cmt = 34 sx C Neat.

10/31 – 11/01/15 SDFWE.

11/02/15

Open well with 0 PSI. ND swedge & valve. NU BOP. PU 3-1/8" drill collar with 3-7/8" bit. Tag cmt in 4-1/2" csg 6' from surface. LD collar. SWI. Shut down due to problems getting reverse unit to location.

11/03/15

MIRU TFH Reverse Unit. NU stripperhead & PU 3-1/8" drill collar & 3-7/8" bit. Tag cmt @ 6.00'. Broke circ. Drill hard cmt from 6.00' down to 24' in 1-1/2 hrs. Clean cmt stringers dwn another 15'. Circ well clean & POOH. PU 4-1/2" retrieving head to +/- 890'. Circ sand off RBP. Latch onto & release RBP. POOH. PU 3-7/8" bit, csg scraper, on 2-3/8" tbg to 2535'. RU swivel & install stripperhead. Clean well out to 2505'. Returns were cmt, paraffin, scale, iron sulfide & sand. Circ well clean in 30 mins. ND stripperhead & swivel. POOH w/bit & scraper. SWI. SDFN.

· · · · · · · · · · · ·

11/04/15 MIRU Tubing Testers. Test 76 jts tbg in the hole to 5000 psi below slips, ok. ND BOP, NU & re-plumb wellhead. Prep for rods. RIH w/pump & rods. Load tbg with FW & test pump to 500 PSI, ok. Return well to production.

ŧ

	Description		Length	Depth
		КВ	6.00'	6.00'
	63	jts 2 ³ / ₈ " J55 EUE 8rd Tubing	2023.26'	2029.26'
<u>_</u> 20	1	41/2"x23/8" TAC w/8000# Tension	2.90'	2032.16'
Tubing	12	jts 2 ³ / ₈ " J55 EUE 8rd Tubing	390.21'	2422.37'
Ē	1	2 ³ / ₈ " Endurance Joint	32.33'	2454.70'
	1	2 ³ / ₈ " Seating Nipple	1.10'	2455.80'
	1	2 ³ / ₈ " Muleshoe MA	15.00'	2470.80'
	1	1¼"x11.00' Polish Rod w/1½" Liner	7.00'	
Rods	1	•		=
	97	³ /4" Rods	2425.00'	
	1	¾" Lift Sub	2.00'	
	1	20-125-10 RXBC Pump	10.00'	

1 ÷

2

.