

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1534657219

Name of Company Burnett Oil Co. Inc. 3080		Contact Leslie Garvis
Address Burnett Plaza - Ste 1500, 801 Cherry St - Unit 9, Ft. Worth, TX 76102		Telephone No. 817-583-8730
Facility Name Gissler A 13		Facility Type Injection Well
Surface Owner BLM	Mineral Owner BLM	API No. 30-015-25683

LOCATION OF RELEASE

Unit Letter B	Section 14	Township 17S	Range 30E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 40 bbls	Volume Recovered 35 bbls
Source of Release Leak in Injection Line	Date and Hour of Occurrence 12/10/15 0800	Date and Hour of Discovery 12/10/15 0800
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - S.Tucker, OCD - H. Patterson	
By Whom? Leslie Garvis	Date and Hour 1249 12/10/15	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

NM OIL CONSERVATION
ARTESIA DISTRICT

DEC 10 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

One inch buried injection line from waterflood to injection well ruptured. Operator was on site when pipe ruptured and the pump at the water station was immediately turned off. The line was repaired and well was returned to injection.

Describe Area Affected and Cleanup Action Taken.*

Shallow berms were dug in order to contain the release on the location therefore the produced water did not leave the well pad. A vac truck was used to collect the produced water and 35 bbls were recovered. Remediation will begin as per BLM & OCD standards once remediation plan has been approved.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Leslie Garvis</i>	Approved by Environmental Specialist: <i>H. Patterson</i>	
Printed Name: Leslie Garvis	Approval Date: 12/11/15	Expiration Date: N/A
Title: Regulatory Coordinator	Conditions of Approval:	
E-mail Address: lgarvis@burnettoil.com	Attached <input type="checkbox"/>	
Date: 12/10/15	Phone: 817-583-8730	

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 11/5/16

2RD-3443

* Attach Additional Sheets If Necessary