

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

DEC 08 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAME NAB1534451906 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company <u>6137</u>	Contact Garry Michael, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-4895
Facility Name Cotton Draw Unit 135H	Facility Type Oil

Surface Owner Federal	Mineral Owner State	API No 30-015-38533
------------------------------	----------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	25S	31E	200	South	1600	West	Eddy

Latitude: N 32°15'27.67"

Longitude: W -103°75'20.49"

NATURE OF RELEASE

Type of Release Spill Oil	Volume of Release 110bbls	Volume Recovered 100bbls
Source of Release Pump housing on LACT unit split in two	Date and Hour of Occurrence November 30, 2015 10:17 AM	Date and Hour of Discovery November 30, 2015 10:17 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones, OCD Jim Amos, BLM	
By Whom? Matt Nettles, Assistant Production Foreman	Date and Hour Kellie Jones, OCD December 1, 2015 10:15 AM Jim Amos, BLM December 1, 2015 10:17 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Pump housing on the LACT unit had split in two causing the oil from oil tanks to spill over. This caused a 110bbl oil release. The valve on the oil tank was shut in to prevent any further release. The pump was repaired.

Describe Area Affected and Cleanup Action Taken.*

110bbls of oil was released on the North, North West side of the facility. 100bbls of oil was recovered via vacuum truck. The affected area was 100'x200'. All released fluid remained on location. Environmental agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Corina Moya</u>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <u>White</u> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: <u>12/10/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>corina.moya@dmv.com</u>	Conditions of Approval:	
Date: 12.3.2015 Phone: 575.746.5587	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>115116</u>	

* Attach Additional Sheets If Necessary

2RP-3437