Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO.	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30- D15-33289 5. Indicate Type of Lease	
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		8-8096	
87505 SLINDRY NOT	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROP			
DIFFERENT RESERVOIR. USE "APPL	TOC 8 State		
PROPOSALS.) 1. Type of Well: Oil Well	8. Well Number 2		
2. Name of Operator	9. OGRID Number		
OXY USA	16696		
3. Address of Operator	10. Pool name or Wildcat		
P.O. Box	Millman Yatos SR QuGBSA, East		
4. Well Location		1	
	: 1650 feet from the Nowth line and	660 feet from the west line	
Section 5	Township 195 Range 29E	NMPM County F224	
Section 5	11. Elevation (Show whether DR, RKB, RT, GR, etc.		
	3375'		
12 Check	Appropriate Box to Indicate Nature of Notice,	Report or Other Data	
12. Oneok	rippropriate box to indicate reactive of recitee,	report of Other Data	
NOTICE OF II	NTENTION TO: 🔑 SUB	SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🗹 📗 REMEDIAL WOF	RK 🔲 ALTERING CASING 🗌	
TEMPORARILY ABANDON	CHANGE PLANS 🔲 COMMENCE DR	ILLING OPNS. P AND A	
PULL OR ALTER CASING		IT JOB 🔲	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM		_	
OTHER:	OTHER:		
	pleted operations. (Clearly str.e all pertinent details, ar		
proposed completion or re	york). SEE RULE 19.15. NMAC. For Multiple Co	impletions: Attach wellbore diagram of	
	•		
T	D-3100' PBTD-3050' Perfs-1222-2624'		
c	F 1011 2 A H O A DOLL	-Circ NM OIL CONSERVATION	
	i-5/8" 24# csg @ 480' w/ 480sx, 12-1/4" hole, TOC-Surf		
5	-1/2" 15.5# csg @ 3100' w/ 725sx, 7-7/8" hole, TOC-Su		
1	DILL P and CIRD @ DECE! MAR D DESCRIPTION 2415!	DEC 1 1 2015	
	RIH & set CIBP @ 2565', M&P 25sx cmt to 2415' RIH & set CIBP @ 2127', M&P 25sx cmt to 1997'		
	RIH & set CIBP @ 2127 , M&P 25sx cmt to 1997	RECEIVED	
	_ ·	NECLIVED	
4. M&P 50sx cmt @ 377' to surface 10# MLF between plugs		Approved for plugging of well bore only.	
Alexander of the first control of		Liability under bond is retained nending regains	
	Above ground steel tanks will be utilized	of C-103 (Subsequent Report of Well Placeting)	
		which may be found at OCD Web Page under Forms, www.cmnrd.state.um.us/ocd.	
Spud Date:	Rig Release Date:		
well bor must be	Plused by 12/15/2016		
	above is true and complete to the best of my knowledg	ge and belief.	
		()	
SIGNATURE	TITLE Sr. Regulatory Advis	or DATE 12/3/15	
Type or print name <u>David Stew</u>	art E-mail address: <u>david_stewart</u>	@oxy.com PHONE: <u>432-685-5717</u>	
For State Use Only			
For State Use Only		1 /	
APPROVED BY:	TITLE DIST AL JOHN	(S) DATE 12/5/2015	
Conditions of Approval (if any):			
		DAIL	
Conditions of Approvar (i. ally).		DATE	
A See	Attached COA's	DATE	

OXY USA Inc. - Proposed TDC 8 State #2 API No. 30-015-33289

CIBP @ 1172' w/ 25sx to 1022'

CIBP @ 2127' w/ 25sx to 1997'


CIBP @ 2565' w/ 25sx to 2415'

PB-3050'

TD-3100'

50sx @ 377'-Surface

12-1/4" hole @ 327' 8-5/8" csg @ 327' w/ 480sx-TOC-Surf-Circ Perfs @ 1222-1244' Ÿ Perfs @ 2177-2197' Perfs @ 2614-2624' 7-7/8" hole @ 3100' 5-1/2" csg @ 3100' w/ 725sx-TOC-Surf-Circ OXY USA Inc. - Current TDC 8 State #2 API No. 30-015-33289



NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:		49		
Well Name 8	k Number:	TOC 8 State	2	
API #:	30 - 0	5-33289		

- 1. Produced water will not be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- 12. 19.15.7.16: B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE: 12/15/15

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).