

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JAN 26 2016

Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

*NAB1603732004* *240737*

Name of Company: BOPCO, L.P.		Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: North Indian Flats 24 Federal #015		Facility Type: Exploration and Production	
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-39137

### OPERATOR

☒ Initial Report ☐ Final Report

### LOCATION OF RELEASE



Unit Letter D	Section 24	Township 21S	Range 28E	Feet from the 330	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.472117° Longitude -104.046462°

### NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 5 bbls	Volume Recovered 3 bbls
Source of Release Stuffing Box	Date and Hour of Occurrence 1/13/2016 time unknown	Date and Hour of Discovery 1/13/2016 10 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Stuffing box packing on the well head failed. The e-pot on the pumping unit shut down the well and the packing was replaced.		
Describe Area Affected and Cleanup Action Taken.* The leak affected 1284 ft <sup>2</sup> of well pad and vacuum trucks recovered standing fluids.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

### OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Amy C. Ruth	Approval Date: 1/26/16	Expiration Date: N/A
Title: EHS Remediation Specialist	Conditions of Approval:	
E-mail Address: ACRuth@basspet.com	Remediation per O.C.D. Rules & Guidelines	
Date: 1/25/2016 Phone: 432-661-0571	Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 2/27/16

2RP-3518

\* Attach Additional Sheets If Necessary