

NM OIL CONSERVATION

ARTESIA DISTRICT

FEB 02 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
RECEIVED
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1604031671

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: COLT STATE SWD #004	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-41401
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 5	Township 25D	Range 28E	Feet from the 1066'	North/South Line North	Feet from the 850	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	------------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.1636543 Longitude -104.1154556

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 2 bbls Oil 325 bbls PW	Volume Recovered: 2 bbls Oil 325 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 1/16/2016 12:00 pm	Date and Hour of Discovery: 1/16/2016 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: Mon 1/18/2016 11:41 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused when a high volume alarm malfunctioned, resulting in the tank overflowing. Vacuum trucks were dispatched to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*
This release occurred within a lined facility. All fluid was able to be recovered, the facility cleaned, repaired, and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert McNeill</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert McNeill	Signed By: <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Environmental Manager	Approval Date: 2/9/16	Expiration Date: N/A
E-mail Address: rmcneill@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: January 30, 2016 Phone: 432-230-0077		

* Attach Additional Sheets if Necessary

2RP-3541