

NM OIL CONSERVATION

ARTESIA DISTRICT

FEB 02 2016

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

hAB1604042514

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: APPLE 5 STATE SWD #001	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-41402
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	5	26S	28E	990'	North	1980'	East	Eddy

Latitude 32.0761986 Longitude -104.107254

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 50 bbls PW	Volume Recovered: 50 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 1/4/2016 12:00 pm	Date and Hour of Discovery: 1/4/2016 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 1/6/2016 3:43 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused when a trucking pump could not operate due to oil tank being at high level. The check valve failed to keep water from flushing back in to trucking tanks from Gun Barrel. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. All fluids were able to be recovered, the facility cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Robert McNeill

Printed Name: Robert McNeill

Title: Environmental Manager

E-mail Address: rmcneill@concho.com

Date: January 18, 2016 Phone: 575-748-6940

Signed By: Mike Bratcher
Approved by Environmental Specialist:

Approval Date: 2/9/16 Expiration Date: N/A

Conditions of Approval: FINAL

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3542