

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 15 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1604739873

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production <i>0137</i>	Contact Leonard Aguilar Production Assistant Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.513.1930
Facility Name Cottontail 16 State Com 1H	Facility Type Oil

Surface Owner State	Mineral Owner State	API No. 30-015-42321
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter O	Section 16	Township 25S	Range 29E	Feet from the 150	North/South Line FSL	Feet from the 1950	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.1230205 Longitude: -103.9866708

NATURE OF RELEASE

Type of Release Spill Produced water & oil	Volume of Release 48 BBL Produced water 5 BBL oil	Volume Recovered 45 BBL produced water 5 BBL oil
Source of Release Flow line ruptured	Date and Hour of Occurrence 2/11/16 @ 2:30 pm	Date and Hour of Discovery 2/11/16 @ 2:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher -OCD	
By Whom? Leonard Aguilar Production Assistant Foreman	Date and Hour 2/11/16 @ 7:58 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

A flow line ruptured causing a spill. Lease operator shut off electronic submersible pump and closed valves to prevent further release. The flow line has been repaired.

Describe Area Affected and Cleanup Action Taken.*

A flow line ruptured causing a release of approximately 48 BBL of produced water and 5 BBL of oil. The spill occurred off pad in a 60' x 15' area on the northeast side of the Cooter 16 State Com 5H well pad. A vacuum truck recovered approximately 45 BBL of produced water and 5 BBL of oil. An environmental agency will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>2/16/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/15/16 Phone: 575.748.1813		

* Attach Additional Sheets If Necessary

2RP-3554