

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

MAR 01 2016

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

**NAB1606239294** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <b>210737</b>	Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Poker Lake Unit 78 Tank Battery	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27536

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	24S	30E	660		660		Eddy

Latitude: 32.194170 Longitude: 103.827430

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 65 barrels PW and 54 barrels Oil	Volume Recovered: 50 barrels oil and 50 barrels PW
Source of Release: Failed HT Gasket	Date and Hour of Occurrence: 2-27-16 @ 1:00pm	Date and Hour of Discovery: 2-27-16 @ 1:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson and Jim Amos BLM	
By Whom? Bradley Blevins via email	Date and Hour: 2-27-16 @ 2:42pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

BOPCO EHS was notified of a release that occurred at the PLU 78 due to a failed heater treater gasket. A vacuum truck was called to the location to recover the fluid within the firewall.

Describe Area Affected and Cleanup Action Taken.\*

The majority of the fluid was contained within the earth berm with the exception of a light overspray on the northern half of the location. A vacuum truck was called to the location and recovered 50 barrels of oil and 50 barrels of produced water from the firewall.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>Bradley Blevins</b>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: <b>[Signature]</b>	
Title: Assistant Remediation Foreman		Approval Date: <b>3/2/16</b>	Expiration Date: <b>NIA</b>
E-mail Address: bblevins@basspet.com		Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: <b>3-1-16</b>	Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: **4/2/16**

**2RD-3576**

\* Attach Additional Sheets If Necessary