	District II Energy Minerals	New Mexico and Natural Resources	Form C-141 Revised June 10, 2003			
	District IV 1220 South	rvation Division h St. Francis Dr.	Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form			
	Santa Fe, NM 87505 Release Notification and Corrective Action					
<b>F</b>		Contact: Pat Ellis			Final Report	
1	Address: 300 North Marienfeld, Suite 600, Midland TX 79701 Telephone No. (432) 685-8100   Facility Name: Amax 24 #8 Facility Type: Tank Battery					
53	Surface Owner BLM Mineral Owner BLM Lease No. NM40655					
	LOCATION OF RELEASE			30-015-27/62		
	Unit Letter Section Township Range Feet from the North	South Line Feet from the	East/West Line	County		
	L 24 23S 31E		1	Eddy		
	NATURE OF DELEASE					
	Type of Release Saltwater Volume of Release 250 barrels			Volume Recovered 240 barrels		
	Source of Release Water transfer pump	Date and Hour of Occurrenc 12/13/2004	1	Hour of Discov 04 8:30 am	′егу	
儞	Was Immediate Notice Given?	If YES, To Whom?				
	Yes No Not Required Linda Nelson / OCD-Artesia   By Whom? Clay Osborn Date and Hour 12/13/2004 10:30 am					
അ						
	Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.				
If a Watercourse was Impacted, Describe Fully.*						
Describe Cause of Problem and Remedial Action Taken.* 1" plug came out of water transfer pump. Picked up 240 barrels produced water out of fire wall.						
	Describe Area Affected and Cleanup Action Taken.* The spill was primarily contained inside the facility dike. The dike was breached in two areas along the west wall with an estimated 6-8 barrels of flu					
running out onto the location pad, and eventually out onto native soils. The spill onto native soils was limited to an area 1'-3' wide and up water with pump trucks.					long. Picked	
<b>a</b>	On December 17, 2004, Highlander personnel inspected the spill area and collected soil samples from inside the facility firewall and the spill area outside the firewall. A total of five (5) auger holes were installed inside the facility firewall, and an additional two (2) auger holes were placed in the spill area off					
	of the well pad. Additionally a drilling rig was utilized to profile the soils. Two (2) bore holes were installed to delineate chloride impact to background levels. New vegetative growth observed in off site spill area.					
3						
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger					
-	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
Sec.12	or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
-	receipt, state, or local laws allow regulations.	OIL CONS	ERVATION	DIVISION		
	Signature: atrick & Ellis		NSERVATION DIVISION Accepted for record NMOCD			
¥	Printed Name: Pat Ellis	Approved by District Supervisor	r: .	3/1/	14 HAR	
		<u> </u>				
9	Title: Division Environmental Safety & Health Supervisor   A	Approval Date:	Expiration I	Date:		
3	E-mail Address: EllisP@pogoproducing.com C	Conditions of Approval:	Λ	Attached		
	Date: 10/24/05 Phone: (432) 685-8100	<u> </u>	V_	L		
E-mail Address: EllisP@pogoproducing.com Date: 10/24/05 Phone: (432) 685-8100 * Attach Additional Sheets If Necessary Oluber release - ent could for Wownentation						
) A		Covenes to tim				
1						