

	OCD Artesia				
	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OM B No 1004-0137 Expires: March 31, 2007 5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS			NM2537		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well □ □ □ Gas Well □ □ Other				Cholla, S Taylor Federal 8. Well Name and No.	
2. Name of Operator Matador Production Company				Cholla 1 Federal #1	
			9. API Well No. 30-015-31187		
3a. Address PO BOX 1936 ~ ROSWELL	3b. Phone No. (include 575.623.6601	e area code)	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Tamano; Bone Spring		
1980' FSL & 1650' FEL, Sec. 1 NWSE, T18S, R31E			11. County or Parish, State		
			Eddy, New Mexico		
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, R	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize After Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Cutre Treat Reclamation Well Integrity W Construction Recomplete Other g and Abandon Temporarily Abandon		
If the proposal is to deepen did Attach the Bond under which following completion of the in	rectionally or recomplete horizontal the work will be performed or provinvolved operations. If the operation final Abandonment Notices shall be the for final inspection.)	ly, give subsurface location ride the Bond No. on file values and the Bond No. on file values in a multiple compared filed only after all requires	ns and measured and to with BLM/BIA. Requir election or recompletion ments, including reclan	ny proposed work and approximate duration thereof we vertical depths of all pertinent markers and zones ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has	
BLM Bond No. NMB000 Surety Bond No. RLB00		00'aea 35	rement		
MIRU PU and POOH w/ production the, pump & rods					

MIRU WL and RIH to set CIBP @ ± 8,550. Load and test casing to 500# RIH and perf 1st Bone Spring Sand from 7,451'-7,164', 7,484'-7,502', 7,554'-7,560'
RIH w/ tubing and packer, set pkr @ ± 7,350'
SEE ATTACHED FOR SEE ATTACHED FOR SEE ATTACHED FOR ARTESIA DISTRICT Acidize @ 7,451'-7,164', 7,484'-7,502', 7,554'-7,560' Swab test Frac @ 7,451'-7,164', 7,484'-7,502', 7,554'-7,560' POOH w/ pkr, RIH w/ production tbg, pump & rods. Put well on Production FEB 2 2 20:0 Accepted for reco... RECEIVED 14. I hereby certify that the foregoing is true and Name (Printed/Typed) Tammy R. Link Title Production Tech MALLE Date THIS SPACE FOR FEDERAL OR STATE ÒFFICE Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or EAU OF LAND MANA CARLSBAD FIELD OF certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. of the United (Instructions on page 2)

thereof





Cholla 1 Federal 1 30-015-31187 Matador Production Company February 12, 2016 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by May 12, 2016.

- 1. Operator shall place CIBP at 8,500' (50'-100' above top most perf) and place 35' of Class H cement on top. WOC and tag.
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails
- **3.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done, C-102 form, and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.

10. See attached for general requirements.

JAM 021216

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>

